

# **Expertise**

Protocol number: 41731149
Order number / reference: 25232862
Inspection date: 25 Sept 2025

Manufacturer: Volkswagen Model: Golf 2.0 TDI SCR Life

VIN: WVWZZZCDZMW118697





# Vehicle details

### Manufacturer / Type / Model / Equipment

Volkswagen Golf 2.0 TDI SCR Life

Vehicle Identification number WVWZZZCDZMW118697

Mileage (Read) 89,716 km
First registration 6 Jul 2021

Number of holders 1

Next periodical technical inspection 07/2026

(Report on hand)

Power / Engine displacement 85 kw / 1,968 ccm

Fuel type / Cylinder

Gearbox / Number of gears

Manual / 6

Type of drive

Type of vehicle

Saloon car

Colour / colour code

Pure White

Colour / Colour code Pule Will

Doors / Seats 5 / 5
Upholstery type Cloth

Colour of upholstery Anthracite-Black

**Vehicle with smoke odor** Yes (not ozone treated)

Driving readiness Roadworthy



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	23,900 km
Last maintenance on / at	12/2024 at 83,524 km		
Key is / should be	2/2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S)
			was not available
		Letter No.	GC295296
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Driving readiness	Roadworthy		
Manufacturer key number/	0603 / CNY 00388		
type code number			
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	Fine dust sticker	
Permitted total weight	1,880 kg	Empty weight	

# Tyres

# **Mounted tyres**

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 94V	All-season tyres on Light alloy	Goodyear	7mm / 7mm
2)	205/55 R16 94V	All-season tyres on Light alloy	Michelin	5mm / 5mm

### Replacement

Тур	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 04/2025		

Legend: Tread depth information for tires on the left is in the first place, for tires on the right is in the second place on the axle in the direction of travel



#### **Equipment**

#### Standard equipment

- · 2 USB-C ports at the front
- · Cornering braking function and evasive assistance
- Airbag: Head airbag system for front and rear passengers including front side airbags
- Exterior mirrors electrically adjustable and heated, with memory function and passenger mirror lowering
- · Brake light, third
- · Headlining in Storm Grey
- · Diesel particulate filter and SCR catalyst
- · Parking assistance
- · Electronic parking brake including auto-hold function
- · Automatic headlight switching with LED daytime running lights
- Front windscreen in laminated safety glass, heat and sound insulating
- · Transmission: 6-speed manual transmission
- · Rear window wiper with interval control
- · ISOFIX anchorage points
- · Rear headrests
- · Paint finish: Uni
- LED taillights
- · Steering wheel: multifunction leather steering wheel
- · Make-up mirrors in the sun visors, illuminated
- · Fatigue detection
- Emergency braking assistant "Front Assist" with pedestrian and cyclist detection
- · Radio "Composition"
- Wheels: Light alloy wheels (4) "Norfolk" 7 J x 16
- Rear seat bench undivided, backrest asymmetrically divided, foldable with center armrest
- · Seat belts: Three-point automatic seat belt for the middle rear seat
- Seat belts: Three-point automatic seat belts in the front with height adjustment and belt tensioner
- · Seats: Lumbar supports in front
- · Lane keeping assistant "Lane Assist"
- 12 volt socket in the luggage compartment
- · Telephone interface with inductive charging function
- · Ambient lighting with logo projection
- · Prepared for "We Connect" and "We Connect Plus"
- · Electronic immobilizer
- · Green thermal insulation glazing, side and rear

- · 2 USB charging ports on the rear center console
- · Airbag for driver and front passenger
- 10-color ambient lighting
- · App Connect
- · Exterior mirror housings and door handles in body color
- · Vehicle tool kit
- Car2X
- · Decorative inlays "Nature Cross Brushed"
- · Digital Cockpit Pro, multi-colored
- · Electronic differential lock XDS
- · Electronic stabilization program and electromechanical brake booster
- · Electric windows, front and rear
- · Pedestrian protection measures expanded
- · Luggage compartment cover
- · Rear window heated
- · Rear spoiler in body color
- · Climatronic air conditioning system
- · Front headrests
- · LED reading lights front (2) and 2 rear
- · LED headlights
- · Dynamic headlight range adjustment
- · Front center armrest height and length adjustable
- Non-smoking version
- · Emergency call service
- · Package: Seat comfort package
- · Tire pressure monitoring indicator (passive)
- · Wheels: Tire Mobility Set
- · Keyless start system without safe lock
- · Electromechanical power steering
- · Seat belts: Three-point automatic seat belts for the outer rear seats
- Seat covers in fabric
- · Seats: Comfort seats in the front
- · Seats: Front seats height adjustable
- · Start-stop system
- · Bumpers in body color
- · Illuminated door handle recesses
- · First aid kit, warning triangle and safety vest
- Warning sound and light for unfastened seat belts at the front and rear
- Central locking without safe security, with radio remote control and 2 radio folding keys

### Extra equipment

- Automatic Distance Control ACC "stop & go" (Automatic Distance Control ACC including speed limiter - Emergency Braking Assistant "Front Assist" with pedestrian and cyclist detection)
- · Rubber mats front
- · Paintwork: Special color Pure White
- Wheels: 4 all-season tires 205/55 R 16
- · Security package



Brief expert findings	
Documents submitted	At the time of the inspection, the registration certificate Part 2 (letter) was available, but the registration certificate
	Part 1 (certificate) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted
	documents was verified during the inspection by the undersigned.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle.
	Lifting equipment and a pit were available for examining the vehicle.
Test drive	No test drive/maneuvering was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
Driving readiness	The vehicle was drivable at the time of inspection.

## Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Trim / covers	Roof lining - Burn hole (cigarettes) - Smart repair
3	Interior	Interior (Rauch) - Odour - Ozone treatment
4	Seat - front	Seat cover - left side - Burn hole (cigarettes) - Smart repair
5	Boot lid / rear door	Trim - standard - lower - Scratched - Replace
6	Trim / covers	Carpet - front left side - Burn hole (cigarettes) - Smart repair
7	Front bumper	Front bumper - Scratched - Paint
8	Roof	Roof - Corrosion - Repair and paint

# Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen with lane departure assistant (ohne Rissbildung) - Stone chips - No deduction
The vehicle shows signs of wear commensurate with its age and use		

The vehicle shows signs of wear commensurate with its age and use.

#### Missing parts

# Description

Trim / covers - Floor mats

### Order/Scope of order

The order was placed to prepare a sales report for the vehicle described. This includes the following:

- · Description of core relevant information about the vehicle
- Documentation of equipment features
  (Delivery by third-party service providers)
- · Documentation of damage, defects, missing parts
- Documentation of previous damage, unrepaired previous damage, repainting
- a brief visual or functional inspection of the equipment details if possible.

  (Functional tests of driver assistance systems are not included in the scope of services!)
- a photo documentation of the vehicle

TÜV SÜD Auto Partner GmbH Gutenbergstr. 13 70771 Leinfelden-Echterdingen Inspection location Hartmann Fleet Professionals GmbH Leerenstraße 25 29683 Bad Fallingbostel



#### Basis for the order

This product is based on the Alphabet Fuhrpark GmbH guidelines for vehicle returns and valuations. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on his or her own expertise.

The vehicle inspection takes place in a disassembled state.

Damage or defects that can only be detected during disassembly/diagnosis work or through advanced knowledge remain within the scope of the prognosis risk. An extended risk exists for concealed defects caused by fraudulent deception and not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted according to the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which in their nature and severity slightly exceed normal use but do not constitute unacceptable damage will be documented and identified under signs of use if necessary.

Damage or defects which, according to the underlying standard, can no longer be attributed to normal use or wear and tear are listed in the product under "Depreciating Factors".

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

#### **Previous damages**

Apparently, no repaired previous damage could be found on the vehicle.





Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear





Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres





Figure 13: Documents



Figure 14: Documents



Figure 15: Documents



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.





Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace





**Damage 2:** Trim / covers: Roof lining - Burn hole (cigarettes) - Smart repair



**Damage 2:** Trim / covers: Roof lining - Burn hole (cigarettes) - Smart repair



**Damage 4:** Seat - front: Seat cover - left side - Burn hole (cigarettes) - Smart repair



**Damage 4:** Seat - front: Seat cover - left side - Burn hole (cigarettes) - Smart repair



**Damage 4:** Seat - front: Seat cover - left side - Burn hole (cigarettes) - Smart repair



**Damage 5:** Boot lid / rear door: Trim - standard - lower - Scratched - Replace





Damage 5: Boot lid / rear door: Trim - standard - lower - Scratched -Replace



Damage 5: Boot lid / rear door: Trim - standard - lower - Scratched -Replace




Damage 6: Trim / covers: Carpet - front left side - Burn hole (cigarettes) -Smart repair



Damage 6: Trim / covers: Carpet - front left side - Burn hole (cigarettes) -Smart repair



Damage 6: Trim / covers: Carpet - front left side - Burn hole (cigarettes) - Damage 7: Front bumper: Front bumper - Scratched - Paint Smart repair







Damage 7: Front bumper: Front bumper - Scratched - Paint



Damage 7: Front bumper: Front bumper - Scratched - Paint




Damage 8: Roof: Roof - Corrosion - Repair and paint



Damage 8: Roof: Roof - Corrosion - Repair and paint




Damage 8: Roof: Roof - Corrosion - Repair and paint



Wear and tear 1: Vehicle glazing: Windscreen with lane departure assistant (ohne Rissbildung) - Stone chips - No deduction





Wear and tear 1: Vehicle glazing: Windscreen with lane departure assistant (ohne Rissbildung) - Stone chips - No deduction



Wear and tear 1: Vehicle glazing: Windscreen with lane departure assistant (ohne Rissbildung) - Stone chips - No deduction



Missing part 1: Trim / covers: Floor mats - Missing - Replace