



VOLKSWAGEN GOLF

GOLF 1.5 ETSI 110KW STYLE DSG

Make	Volkswagen
Model	Golf
VIN	WVWZZZCDZMW306137
Registration	J423RL
First registration date	10/5/2020
Power kW	110 kW
Body colour	Urano Grey Uni
Mileage	88,966
Administrative mileage	88,966

INSPECTION DETAILS

Customer	Alphabet Nederland B.V.
Inspection - ID	8118783

Inspection date	4/2/2025 10:45:30 AM
Inspection location	Innamestraat Alphabet B.V.

VEHICLE INFO

Body colour	Urano Grey Uni
Fuel type	Hybrid Petrol
Fuel Level	100
Gearbox	Automatic
Transmission	Front
Number of seats	5
Central consol F	Yes
Tyre type FL	Summer
Tyre make FL	261
Tyre size FL	225/45 R 17 091 W
Tyre profile depth FL	3.80
Tyre type RL	Summer

Tyre make RL	261
Tyre size RL	225/45 R 17 091 W
Tyre profile depth RL	4
Tyre type FR	Summer
Tyre make FR	261
Tyre size FR	225/45 R 17 091 W
Tyre profile depth FR	3.90
Tyre type RR	Summer
Tyre make RR	261
Tyre size RR	225/45 R 17 091 W
Tyre profile depth RR	5.70

DOCUMENTS AND MAINTENANCE

Number of keys total	2	Registration Certificate	Yes
User's manual	Yes	Registration Certificate	Original

EQUIPMENT ACCORDING TO INSPECTOR

Windows electric F	Yes	Rear parking sensors	Yes	Paint type	Opaque
Front parking sensors	Yes	Headlights Xenon/LED/Laser	Yes		

DAMAGES



2 | WING RL

Type	Scratch(es)
Repair mode	Polish
Comments: en chemische schade	



3 | DOOR RL

Type	Scratch(es)
Repair mode	Polish




4 | DOOR FL

Type	Scratch(es)
Repair mode	Repair and paint (complete)




6 | WINDSCREEN

Type	Stone chip(s)
Repair mode	Windscreen repair



8 | WING RR


Type	Scratch(es)
Repair mode	Repair and paint (complete)



9 | DOOR RR


Type	Scratch(es)
Repair mode	Repair and paint (complete)

Comments: en polijstbare krassen



10 | REAR WINDOW

Type	Scratch(es)
Repair mode	Replace



COMMERCIAL PHOTOS

