



Volkswagen Golf: 2BXV301

Vinnumber:	WVWZZZCDZNW162114	Versionname:	
First Registrationdate:	4/05/2022	Fiscalpower:	
Expertise Mileage:	75225	Power Kw:	81
Bodytype:		Body colour:	Blue
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	1406
Fueltype:	Petrol		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Radio multimedia:		Type of Tow bar:	No Tow bar
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Degree of wear

205/55/16/92 H				
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/55 R 16 92 H
Tyre size FR				205/55 R 16 92 H
Tyre size RL				205/55 R 16 92 H
Tyre size RR				205/55 R 16 92 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				256
Tyre make FR				261
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT	1358,61
-------------------	---------

Centre console, Glue residues, Cleaning	28,43
---	-------



Bumper F, Chemical polution, Polish

0,00



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)

478,65



Door RL, Scratch(es), Repair and paint (complete)

434,50



Alloy rim FL, Scratch(es), Repair and paint (complete)

129,66



Outside rear-view mirror housing L, Bad repair, Repair and paint (complete)

157,71



Alloy rim FR, Scratch(es), Repair and paint (complete)

129,66



Step R, Scratch(es), Acceptable

0,00



Bodywork, Glue residues, Acceptable

0,00



Roof, Dent(s), Acceptable

0,00

