



TOYOTA PROACE VERSO: 1YGA615

Vinnnumber:	YARVAYHVKGZ183818	Versionname:	1.5D 88kW MWB Shuttle
First Registrationdate:	19/08/2020	Fiscalpower:	
Expertise Mileage:	187140	Power Kw:	88
Bodytype:		Body colour:	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:		Parking lot:	3407
Fueltype:	Diesel		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Front parking sensors:	
Cruise Control:		Rear parking sensors:	
Steering wheel multifunctional:		Type of Tow bar:	No Tow bar
Type of headlighting:	Headlighting Halogen		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		
Type of GPS storage:	HD		

Limited Technical Inspection

Degree of wear

215/65/16/109 R				
Winter tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				215/65 R 16 109 R
Tyre size FR				215/65 R 16 109 R
Tyre size RL				215/65 R 16 109 R
Tyre size RR				215/65 R 16 109 R
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				265
Tyre make FR				265
Tyre make RL				265
Tyre make RR				256

Assistance equipment

Emergency spare wheel:	Yes	Jack:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT:	998,18
Interior, Damaged, Acceptable:	0,00



Floor covering R, Damaged, Forfeit

52,18



Floor covering FL, Hole, Replace

152,63



Interior covering A pillar L, Dirty, Cleaning

28,43



Engine insulation, Damaged, Replace

0,00



Bumper F, Scratch(es), Spot repair

144,58



Wheel cover FL, Scratch(es), Replace

25,00



Outside rear-view mirror housing L, Scratch(es), Acceptable

0,00



Door FL, Dent(s) and scratch(es), Repair and paint (complete)

434,50

DOOR RL, Dent(s) and scratch(es), repair and paint (complete)

43,00



Wing RL, Dent(s), Paintless dent repair

93,06



Wheel cover RL, Scratch(es), Acceptable

0,00



Internal boot lining R, Scratch(es), Replace

42,80



Wing RR, Scratch(es), Acceptable

0,00



Door RR, Scratch(es), Acceptable

0,00



Wheel cover RR, Scratch(es), Replace

25,00



Outside rear-view mirror housing R, Scratch(es), Acceptable

0,00

