



Expertise

Protocol number: 41228948
Order No. / Reference: 25124708
Inspection date: 25 Aug 2025

Manufacturer: Volvo

Model: XC90 B5 D AWD Geartronic Momentum Pro

VIN: YV1LCK2VCN1800080



Vehicle details	
Manufacturer / Type / Model / Equipment	
Volvo XC90 B5 D AWD Geartronic Momentum Pro	
Vehicle Identification number	YV1LCK2VCN1800080
Mileage (Read)	179,168 km
First registration	8 Nov 2021
Number of holders	1
Next periodical technical inspection	03/2027
(Report on hand)	
Power / Engine displacement	173 kw / 1,969 ccm
Fuel type / Cylinder	Hybrid Diesel / E / 4
Gearbox / Number of gears	Automatic / 8
Type of drive	All-wheel drive
Type of vehicle	SUV
Colour / colour code	Savile Grau-Metallic
Doors / Seats	5 / 5
Upholstery type	Leather
Colour of upholstery	Black



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	4,039 km
Last maintenance on / at	01/2025 at 153,206 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available
		Letter No.	GC688167
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	9101 / BPR 00075		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	Fine dust sticker	
Permitted total weight	2,670 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 105V	Summer tyres on Light alloy	Continental	5mm / 5mm
2)	235/55 R19 105V	Summer tyres on Light alloy	Continental	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/60 R18 107V	Winter tyres on Light alloy	Semperit	5mm / 5mm
2)	235/60 R18 107V	Winter tyres on Light alloy	Semperit	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 09/2025		

Legend: Tread depth information for tires on the left is in the first place, for tires on the right is in the second place on the axle in the direction of travel



Equipment

Standard equipment

- ABS - Anti-lock braking system
- Airbag, passenger side can be switched off
- Airbag, knee airbag for driver
- Active seat belts with belt tensioners (for all passengers)
- All-wheel drive (AWD)
- Exterior mirrors electrically adjustable, foldable and heated
- Fastening system for carrier bags in the luggage compartment
- Condensation sensor for automatic activation of the defroster function
- Brake energy recovery
- Brake lights, adaptive
- City Safety
- Connected Safety
- Roof spoiler
- Digital instrumentation
- Drive Mode (driving mode settings for engine, transmission, steering, brakes and chassis)
- Electronic differential lock
- Electric windows front and rear
- Luggage compartment partition net
- Transmission: 8-speed Geartronic automatic transmission
- Automatic tailgate
- Rear window wiper with interval function
- Interior lighting
- IntelliSafe Assistant
- ISOFIX mount for the outer rear seats
- Keyless start
- Automatic climate control with separate temperature control for driver and passenger side
- Front headrests
- Steering wheel adjustable for height and length
- Make-up mirrors for driver and passenger, illuminated
- Model and engine emblem on the rear
- Oncoming Lane Mitigation
- Parking brake (electric)
- Upholstery: Leather comfort seats
- Radio accessories: Two USB-C interfaces on the back of the tunnel console
- Tire pressure monitoring system
- Road Sign Information (RSI) - Traffic Sign Recognition
- Wheels: 19" 5-spoke black alloy wheels
- Rear seat bench of the 2nd row in 40/20/40 ratio or completely foldable
- Safety braking system with disc brakes all around (internally ventilated)
- Seats: Lumbar support (2-way adjustable) for driver and passenger seat
- Driver and passenger side airbags with two-stage deployment system
- Airbag, side airbags for driver and front passenger and curtain/shoulder airbags (IC) for all occupants
- Attention warning
- Outside temperature display
- Hill Descent Control HDC
- Hill Start Assist (HSA)
- Indicators (LED) integrated in exterior mirrors
- On-board computer
- Brake light, third
- Chrome applications
- CleanZone air quality system with activated carbon filter
- Aluminum roof rails (integrated)
- diesel particulate filter
- tachometer
- Aluminum door sills with Volvo logo at the front (illuminated) and rear
- Electronic stability control
- Automatic brake
- Cruise control system
- Belt height adjustment front and rear (2nd row of seats)
- Rear window, heated
- Interior and exterior mirrors automatically dimming
- Intelligent driver information system
- IntelliSafe Surround
- Keyless Drive
- Parental controls
- Headrests of the 2nd row of seats can be folded down (electrically)
- Load compartment blind (semi-automatic)
- Steering wheel: Multifunction buttons on the steering wheel
- Front center armrest including cup holder
- Sensus navigation system
- Package: Winter Package
- Pollen filter
- Radio accessories: Smartphone integration Apple CarPlay and Android Auto
- Rain sensor
- Road Edge Detection
- Run-off Road Protection
- Wheels: Tire sealant
- Sensus Connect infotainment system
- Power steering, speed-dependent
- Seats: Driver and passenger seats height adjustable (electrically)
- Start/Stop technology
- Power socket
- First aid kit and warning triangle
- Volvo On Call with Wi-Fi hotspot



- Textile floor mats
- Lashing eyes in the luggage compartment (foldable)
- Preparation for Trailer Stability Control (TSA)
- WHIPS whiplash protection system

- Immobiliser
- Central locking with two radio remote controls and integrated emergency key

Extra equipment

- Head-up display: Graphic display of driving information in the windscreen
- Package: Parking assistance package (front and rear parking sensors - rear view camera)
- Panoramic glass sunroof with lifting function (electric) (with integrated, continuously adjustable sunshade)
- Parking aid, front and rear
- Rear view camera
- Trailer hitch (semi-electric)
- Package: Lighting package (LED fog lights (integrated in the front spoiler) - headlight cleaning system - full-LED "Thor's Hammer" Active High Beam headlights with extended high beam, dynamic cornering light, intelligent high beam assist with adaptive headlight range control, and integrated LED daytime running lights - ambient lighting (multi-color) front and rear; on the doors - exit lights in the rear doors - rear footwell lighting - illuminated cup holders in the front - work light on the trunk lid)
- Paintwork: metallic paint

Brief expert findings

Documents submitted	At the time of the inspection, the registration certificate Part 2 (letter) was available, but the registration certificate Part 1 (certificate) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was verified during the inspection by the undersigned.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and a pit were available for examining the vehicle.
Test drive	No test drive/maneuvering was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Mudguard - right side	Mudguard - right side - Scratch(es) - Smart repair
2	Trim / covers	Door trim - rear left side - Deformed - Smart repair
3	Trim / covers	Door trim - rear right side - Deformed - Smart repair
4	Side panel - rear left side	Wheel well extension - Scratch(es) - Smart repair
5	Sill - right side	Sill - Scratch(es) - Smart repair
6	Engine	Engine cover - top / cover - Damage caused by marten / rodent - Replace
7	Side panel - rear left side	Sill - Dent / paintcoat damage - Smart repair
8	Door - rear left side	Door - Scratch(es) - Paint
9	Bonnet	Bonnet - Scratch(es) - Paint
10	Vehicle glazing	Windscreen (Riß) - Broken / torn - repair according to calculation

Wear and tear

No.	Component group	Description
1	Sill - left side	Sill - Scratch(es) - No deduction
2	Body	Body (Waschanlagenkratzer) - Scratch(es) - No deduction
3	Side panel - rear right side	Wheel well extension - Scratch(es) - No deduction
4	Trim / covers	Boot lid - interior trim - Scratch(es) - No deduction
5	Wheel / tyres	Alloy rim - front left side - Scratch(es) - No deduction
6	Wheel / tyres	Alloy rim - front right side - Scratch(es) - No deduction



No.	Component group	Description
7	Interior	Interior - Scratch(es) - No deduction

The vehicle shows signs of wear commensurate with its age and use.

Missing parts

Description

Interior - Separation net (Gepäckraum Trennnetz)

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Provided by user / customer, from 17 Jul 2025	1.347,47 €
2	Front, Provided by user / customer, from 17 Jul 2025	2.739,93 €
3	Side right, Provided by user / customer, from 17 Jul 2025	2.758,82 €
4	Rear, Provided by user / customer	

Repainting

No. Repainting

- Boot lid / rear door, Professionally carried out, Invoice of repair done Non-existent
- Door - rear right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Boot lid / rear door	274 µm	Door - rear right side	160 µm
----------------------	--------	------------------------	--------

Order/Scope of order

The order was placed to prepare a sales report for the vehicle described. This includes the following:

- Description of core relevant information about the vehicle
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of previous damage, unrepaired previous damage, repainting
- a brief visual or functional inspection of the equipment details if possible.
(Functional tests of driver assistance systems are not included in the scope of services!)
- a photo documentation of the vehicle



Basis for the order

This product is based on the Alphabet Fuhrpark GmbH guidelines for vehicle returns and valuations. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on his or her own expertise.

The vehicle inspection takes place in a disassembled state.

Damage or defects that can only be detected during disassembly/diagnosis work or through advanced knowledge remain within the scope of the prognosis risk. An extended risk exists for concealed defects caused by fraudulent deception and not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted according to the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which in their nature and severity slightly exceed normal use but do not constitute unacceptable damage will be documented and identified under signs of use if necessary.

Damage or defects which, according to the underlying standard, can no longer be attributed to normal use or wear and tear are listed in the product under "Depreciating Factors".

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Die Beiliegenden Räder sind kein Teil der Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Documents




Figure 17: Documents



Figure 18: Additional tyres



Figure 19: Navigation



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Damage 1: Mudguard - right side: Mudguard - right side - Scratch(es) - Smart repair



Damage 1: Mudguard - right side: Mudguard - right side - Scratch(es) - Smart repair



Damage 2: Trim / covers: Door trim - rear left side - Deformed - Smart repair




Damage 2: Trim / covers: Door trim - rear left side - Deformed - Smart repair



Damage 3: Trim / covers: Door trim - rear right side - Deformed - Smart repair



Damage 3: Trim / covers: Door trim - rear right side - Deformed - Smart repair




Damage 4: Side panel - rear left side: Wheel well extension - Scratch(es) - Smart repair



Damage 4: Side panel - rear left side: Wheel well extension - Scratch(es) - Smart repair



Damage 5: Sill - right side: Sill - Scratch(es) - Smart repair




Damage 5: Sill - right side: Sill - Scratch(es) - Smart repair



Damage 6: Engine: Engine cover - top / cover - Damage caused by marten / rodent - Replace



Damage 6: Engine: Engine cover - top / cover - Damage caused by marten / rodent - Replace




Damage 7: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



Damage 7: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



Damage 7: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



Damage 7: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



Damage 7: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



Damage 7: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



Damage 8: Door - rear left side: Door - Scratch(es) - Paint



Damage 8: Door - rear left side: Door - Scratch(es) - Paint




Damage 8: Door - rear left side: Door - Scratch(es) - Paint



Damage 8: Door - rear left side: Door - Scratch(es) - Paint




Damage 9: Bonnet: Bonnet - Scratch(es) - Paint



Damage 9: Bonnet: Bonnet - Scratch(es) - Paint




Damage 9: Bonnet: Bonnet - Scratch(es) - Paint



Damage 9: Bonnet: Bonnet - Scratch(es) - Paint



Damage 9: Bonnet: Bonnet - Scratch(es) - Paint



Damage 9: Bonnet: Bonnet - Scratch(es) - Paint



Damage 10: Vehicle glazing: Windscreen (Riß) - Broken / torn - repair according to calculation



Damage 10: Vehicle glazing: Windscreen (Riß) - Broken / torn - repair according to calculation



Damage 10: Vehicle glazing: Windscreen (Riß) - Broken / torn - repair according to calculation



Repainting 1: Boot lid / rear door



Repainting 1: Boot lid / rear door



Repainting 2: Door - rear right side



Repainting 2: Door - rear right side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: YV1LCK2VCN1800080
Hersteller / Modell: VOLVO VOLVO XC90 B5 D AWD Geartronic Momentum Pro

Datum	KM-Stand	Beschreibung
18.03.2025	161.228	AU; Dieselpartikelfilter ern
31.01.2025	153.206	AU; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
02.04.2024	112.712	Reparatur Sonstiges; Systemtest/Eigendiagnose
20.02.2024	112.712	Reparatur Sonstiges; Reparatur Sonstiges; Systemtest/Eigendiagnose; Systemtest/Eigendiagnose
25.01.2024	112.519	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Reparatur Sonstiges; Wartung Sonstiges
02.09.2023	97.728	Bremse Sonstiges; Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben vorne
05.04.2023	73.469	Bremsklötze hinten; Bremsklötze vorne; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Reparatur Sonstiges; Wartung Sonstiges
25.08.2022	41.340	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges