



VOLVO XC90
XC90 T8 Twin Engine 320+87 ch Geartronic
7pl Inscription Luxe

VIN NO YV1LFBABDH1146117
Registration Number EG338SB



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	-	2	155009 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2024-08-16	138647	2016-11-14	-

Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20250925130427
Inspection Date / Place	2025-09-25 / BCA MITRY	Cosmetic Grade	3


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Exempt Rate
Fuel Type	Plug - in Hybrid Electric Vehicle Petrol	Gearbox Type	Automatic
Colour	Blue	Engine Size (cc)	1969
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	7
Charging Cables		NEDC CO2 Rating (q/km)	49

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			







Equipment

Central locking	Electrically folding wing mirrors	Rear parking sensors	Electric Tailgate
Cruise control	Power assisted steering	Electrically adjustable seats	Radio
Alloys wheels	Stability control	Front parking sensors	Satellite navigation

Equipment Details


Seat Heating	Front	Air Conditioning	Yes
Sunroof Type	Tilt/Slide Glass		

Wheels & Tyres

Left Front Tyre Depth	4	Left Rear Tyre Depth	5
Right Rear Tyre Depth	5	Right Front Tyre Depth	5

Cosmetic Damage

9 Dommages



0 Dommages



Component		Damage	Comments
1	Bumper / Back	Paint / Scratch / Line	
2	Rim	Out of Bodywork / Scratch	
3	Rim	Out of Bodywork / Scratch	
4	Tire / Front Left	Tire	
5	Windshield / Front	Glass Break	
6	Rim	Out of Bodywork / Scratch	
7	Door / Front Right	Bodywork / Dent / Deformation	
8	Door / Back Right	Bodywork / Dent / Hail Area	
9	Rim Brake pads	Out of Bodywork / Scratch	



1. Bumper / Back
Paint / Scratch / Line -




2. Rim
Out of Bodywork / Scratch -



3. Rim
Out of Bodywork / Scratch -



4. Tire / Front Left
Tire -



5. Windshield / Front
Glass Break -



6. Rim
Out of Bodywork / Scratch -



7. Door / Front Right
Bodywork / Dent / Deformation -



8. Door / Back Right
Bodywork / Dent / Hail Area -














9. Rim Brake pads
Out of Bodywork / Scratch -

Mechanical Condition









Tyres

Presence Anti-Theft Lock Nut 

Dashboard Lights

ABS Warning Light		Diesel Particulate Filter Light	
4WD Light		Dashboard Working	
Engine Light		Oil Pressure Warning Light	
Airbag Warning Light		Brake Warning Light	
Level - Fuel / Battery	50	Transmission Warning Light	
ESP Fault/Traction Control Malfunction Light		Service Light	
Steering Fluid Level	NA		

Equipments Test

Convertible, Sunroof, Wagon, Flatbed truck, Tailgate electrics test		Dump / Trail / Tail Gate Lift	NA
Main & Spare Keys Functioning		Central Locking	
Electric Windows		Audio Equipment	
Navigation System		AC / Heating System	
Parking Sensors / Cameras Functioning			

Levels

Oil - Condition	NA	Level - Oil	Not available
Coolant Fluid - Condition		Coolant Fluid	
Brakes Fluid			

Engine

Cross Member		Serpentine Belt	
Control Liquid Leak			

Hybrid/EV

Charge Port Condition		Charge lead 1 condition /Charge lead 2 condition	
-----------------------	---	--	---

Hybrid System Fault ✓

Test Drive Inspection

Test Drive			
Vehicle Starts	✓	Engine functioning	✓
Engine / Aux Belt / Pulley Noise	✓	Steering Noise/Gripping	✓
Smoke Quantity	✓	Transmission	✓
Engine Power	✓	Clutch Functioning	✓
Steering	✓	Brakes Functioning	✓
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.