



status report

customer:	BCA Autoauktionen GmbH
report Number:	0000001256008-EN18

vehicle data			
Volvo XC90 (09.2014->) Plus Dark AWD			
Vehicle identification number	YV1LFK2V6P1952130	mileage read:	40431 km
..			
First Registration / construction year:	24.03.2023 / 2022	Visit Date / place of birth:	31.07.2025 Neuss
Bodywork:	SUV	Re - import:	unknown
Body type:	hatchback	KBA no. :	9101//BPR
Fuel / emission class:	diesel / -	transmission type:	automatic
Displacement / power:	1969 ccm / 173 kW (235 PS)	Engine:	-
paint:	PLATINUM GREY / Metallic	Number of previous owners:	-
Doors / seats:	5 / 7	number keys:	1
Next HU / AU:	- / -	cushion type:	-
Service book available:	yes	Interior Color:	black
smoking vehicle:	no	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle	-	state outside:	3 - Average
documents:			
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)			
GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	1	yes / -	- / -
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires

Tyre / wheel type:	All season tires	polished aluminum
1st axis - Left / states .	Goodyear	275/45/R20/110W 5 mm
1st axis - right / states .	Goodyear	275/45/R20/110W 5 mm
2nd axis - Left / states .	Goodyear	275/45/R20/110W 5 mm
2nd axis - right / states .	Goodyear	275/45/R20/110W 5 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment

- | | |
|---|--|
| <ul style="list-style-type: none"> • 3.Sitzreihe • Airbag switched off • Ambient lighting • Anti-Blockier-System (ABS) • • Audiosystem High Performance Pro by Harman-Kardon
<i>Subwoofer</i> • • Power side mirrors . adjustable and heated • Outside temperature display • Indicator LED integrated in the exterior mirror • Brake Energy Regeneration • Digital instrumentation 12.3 "display • Door sill trims with aluminum inlay • First aid kit / first aid kit • Driver Assistance package
<i>Geschwindigkeits-Regelanlage (Tempomat) mit Abstandsregelung, Fahrassistentz-System: Emergency Stop Assist, Fahrassistentz-System: Pilot Assist</i> • Fahrassistentz-Paket Safety Assistance
<i>Fahrassistentz-System: Verkehrszeichenerkennung (Road Sign Information, RSI), Geschwindigkeits-Regelanlage (Tempomat), Geschwindigkeits-Begrenzeranlage, Fahrassistentz-System: City-Safety-System (Autonomer Notbrems-Assistent), Fahrassistentz-System: Bremsassistent, Fahrassistentz-System: Straßenrand-Erkennung (Road Edge Detection), Fahrassistentz-System: Connected Safety, Fahrassistentz-System: aktiver Spurhalteassistent (LKA), Fahrassistentz-System: Oncoming Lane Mitigation, Fahrassistentz-System: Müdigkeits-Warner (Driver-Alert-Control, DAC), Fahrassistentz-System: Ready to Drive Notification</i> | <ul style="list-style-type: none"> • Airbag passenger side • Airbag driver side • Trailer stabilization program (TSA) Preparation • Drive all-wheel drive • Leather-look dashboard with contrasting stitching • Automatic driving light / light sensor • Outside mirror electr. anklappbar
<i>Bodenleuchte im Außenspiegel</i> • Mirrors black , high-gloss • Operating tailgate / lids automatically • board computer • Roof rails black , high-gloss • Parking assistance front and rear (rear with brake function) • Elektron. Differentialsperre Corner Traction Control (CTC) mit Torque Vectoring • Exterior scopes painted • Driver Awareness driving assistance package
<i>Fahrassistentz-System: Totwinkel-Assistent (Blind Spot Informations System, BLIS), Fahrassistentz-System: Heckaufprall-Abschwächung, Fahrassistentz-System: Querverkehrs-Assistent Heck (Cross Traffic Alert, CTA)</i> • Automatic stability control • Fahrassistentz-System Berganfahr-Assistent (HSA) • • Luggage compartment partition (net) • Transmission Automatic - Geartronik (8-step) • Induction charging cradle for smartphone • pollen filter • Body 5-door • Keyless Start |
|---|--|

• Driving Assistance System Hill Descent Control (HDC) • Fahrassistenz-System Multikollisionsbremse (Multi Collision Brake) • Electric windows front + rear • Luggage compartment cover / shade • Rear window heatable • Infotainment-System Android (DAB+) <i>Service-System: Google Services</i> • Isofix seats for child seat • Keyless Drive • • 2-zone automatic climate control • Head airbag system • • steering wheel heating • Steering column (steering wheel) longitudinally adjustable • Air Quality Monitoring System (Clean Zone Interior Package CZIP) • Mild-Hybrid 183 kW (Motor 2,0 Ltr. - 173 kW Diesel) • facelift • Wheelbase 2984 mm • Tire pressure monitoring system • Rear seat 3-piece • Low-emission according to the Euro 6d exhaust gas standard • Whiplash protection system (WHIPS) • Sensor disc fitting detection • Seat belts front and rear adjustable in height • Roller blind on rear side windows • Socket (12V) port in the trunk / cargo area • Bag hook in the luggage compartment • • • immobilizer • Central locking with remote control	• Integrated child seat (2nd row of seats in the middle) • Knee airbag , driver's side • Rear headrests electr. folding • Steering wheel with multifunction • Steering column (steering wheel) height adjustable • LM rims • Illuminated make-up mirror • Front center armrest with cup holders • Park brake electric • Tire repair kit • Rußpartikelfilter • Rear seat backs foldable • Rain-sensing wipers • Side airbag in front • • Seat comfort package <i>Sitz vorn links elektr. verstellbar (mit Memory), Sitz vorn rechts elektr. verstellbar (mit Memory), Memoryfunktion für Sitz vorn rechts, Beinauflage elektr. verstellbar, Sitze vorn, Lendenwirbelstützen vorn, elektr. verstellbar (4-Wege)</i> • Start / Stop system • Front bumper with high-gloss black applications • The textile foot mat Premium • Glazed tinted • Warning system for seat belts front and rear • <i>Sitzheizung vorn, Sitzheizung hinten</i>
---	--

special Features	
• Towbar semi-electric • Metallic paint •	• Light package <i>Scheinwerfer LED mit adaptiver Lichtverteilung (Intelligent Light System), Nebelscheinwerfer LED mit integriertem Abbiegelicht, Fahrassistenz-System: Fernlichtassistent,</i>

- Sports seats in nappa leather / man-made leather
*Innenausstattung: Dekoreinlagen Aluminium Metall Mesh,
 Schalt-/Wählhebelgriff Kristallglas, Lenkrad (Sport)*

- Scheinwerfer-Reinigungsanlage (SRA)*
- Rearview Camera with 360 ° Surround View
Rückfahrkamera
 - Darkened rear side windows and rear windscreen

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Mileage plausible: not testable
 not testable

reference:

Note Road Safe:

Accident injury assessment

Rep. Predamages / -height gross: no detectable

As part of a paint film thickness measuring the body outer skin no previous damage could be detected .

Layers of paint thickness measurement:

Within the tolerances

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.

Existing collision damage:

-
 -

reference:

Overview conducted technology audit

coupling:	✓ examined limited	engine running:	✓ examined limited
transmission:	✓ examined limited		

Performed testing technology

coupling:	The clutch could be tested only limited within the test drive / pull test .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Das Fahrzeug hat Laufleistungs und Altersbedingte Gebrauchsspuren. Kosten und Schadenserweiterung sind möglich. Die Fahrzeugfront hat Steinschläge. Schäden sind nicht ausgeschlossen.

damage



	component	Damage	Rep kind
1.	Wartung	Due	
2.	Trunk lining law	Scrape	
3.	Trunk lining left	Scrape	
4.		Dirty (animal hair)	
5.	Rear bumper	Scratch(es)	
6.	Diffusor	Scrape	
7.		Damaged	
8.	Key with remote control	Missing	
9.		Damaged	
10.	Sunroof	Chipping from stones	
11.	Windshield	Chipping from stones in field of view	
12.		Scrape	
13.	Outside mirror - right	Scratch(es)	
14.	Sitz - Vorne - Rechts: Kissen	Damaged	
15.		Damaged	
16.	Zierleiste Vorne - Mitte	Scratch(es)	
17.	Door Rear - right	Scratch(es)	
18.	exterior body	Surface scratch(es)	
19.	Moulding Rear - right	Damaged	
20.	Sidewall - Rear - right	Scratch(es)	
21.		Wear and tear	
22.	hood	Wear and tear	
23.	Taillight left	Scratch(es)	
24.	rear window	Sticker	

The expert points out that the vehicle in addition to the age- damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



trunk



instrument cluster



mileage



filler cap



rims



rims



rims




rims



VIN




service book



service book



Others



Others




Others



Others




interior rear



Navigation system



Drivers side + Steering Wheel + center console



2. Trunk lining law

Scrape



2. Trunk lining law

Scrape



3. Trunk lining left

Scrape



3. Trunk lining left

Scrape




4.

Dirty (animal hair)



4.

Dirty (animal hair)



5. Rear bumper

Scratch(es)



5. Rear bumper

Scratch(es)



6. Diffusor

Scrape



6. Diffusor

Scrape



6. Diffusor

Scrape




7.

Damaged



9.

Damaged



9.

Damaged



10. Sunroof

Chipping from stones



10. Sunroof

Chipping from stones



11. Windshield

Chipping from stones in field of view



11. Windshield

Chipping from stones in field of view



12.

Scrape



12. **Scrape**



13. Outside mirror - right **Scratch(es)**



14. Sitz - Vorne - Rechts: Kissen **Damaged**



14. Sitz - Vorne - Rechts: Kissen **Damaged**



15. **Damaged**




16. Zierleiste Vorne - Mitte **Scratch(es)**



17. Door Rear - right

Scratch(es)



17. Door Rear - right

Scratch(es)



18. exterior body

Surface scratch(es)



18. exterior body

Surface scratch(es)



19. Moulding Rear - right

Damaged



19. Moulding Rear - right

Damaged



20. Sidewall - Rear - right

Scratch(es)



20. Sidewall - Rear - right

Scratch(es)



21.

Wear and tear



21.

Wear and tear



21.

Wear and tear



21.

Wear and tear



22. hood

Wear and tear



22. hood

Wear and tear




23. Taillight left

Scratch(es)



23. Taillight left

Scratch(es)



24. rear window

Sticker