

Inspection Protocol

VOLVO V90 CROSS COUNTRY B4 AWD

Vehicle information

| | | | |
|-----------------------------|------------|---------------------------------------|--------------------------|
| License plate | HYW38R | Inspected by | R.A. |
| Year model | 2022 | Date of inspection | 2025-07-10 |
| Manuf. year/month | 2021-12 | City | Falkenberg |
| First day in traffic | 2021-12 | Keys | 2 |
| Colour | Grå | Service book | Saknas |
| Mileage | 57 980 km | Latest service | - |
| Fuel | Diesel | Mileage at the latest service- | |
| Transmission | Geartronic | Summer tires | 19" alu-fälg 5/5/5/5 |
| Engine effect | 145 kW | Winter tires | alu-fälg odubbat 8/8/7/7 |

Damages

| Location | Damage | Comments | Costs excluding VAT |
|-----------------------|-------------------|-----------------|----------------------------|
| Service, Service book | Missing | | 360 € |
| Other, Other | Other | Sliten ratt | - |
| Door, Rear left | Smart repair | | 70 € |
| Bumper, Rear | Smart repair | | 70 € |
| Bumper, Front | Smart repair | | 70 € |
| Glass, Windshield | Stenskott/Spricka | | - |
| Rims, Aluminum rim | Damage | Sommarfälg vb | 220 € |
| Rims, Aluminum rim | Damage | Vinterfälg | 220 € |

Total excl. VAT 1 010 €

Images

[See all images in large format](#)

































