



status report

customer: Santander Consumer Leasing GmbH

reference:

vehicle data

Volvo XC60 R Design 2WD

Vehicle identification number	YV1UZK5VDN1071332	mileage read:	127119 km
First Registration / construction year:	14.12.2022 / 2022	Visit Date / place of birth:	12.09.2025 Hoppegarten
Bodywork:	SUV	Re - import:	no
Body type:	hatchback	KBA no. :	9101//BTJ
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	1969 ccm / 145 kW (197 PS)	Engine:	front-wheel drive
paint:	CRYSTAL WHITE / Metallic	Number of previous owners:	1
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	Leather / fabric
Service book available:	yes	Interior Color:	black
smoking vehicle:	no	Last service km / on the:	103273 / 17.12.2024
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle	Eg II (veh - letter)	state outside:	2 - Good
documents:			
visit condition:	-	condition inside:	2 - Good
state general:	2 - Good		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
Hard Disk Drive	2	yes / yes	103273 / 17.12.2024
☒ Fernbed . Auxiliary heating	☒ partition net	☒ Wind Deflector	☒ AHK fixed
☒ AHK removable	☒ AHK swivel	☒ AHK key	☒ Fernbed . entertainment
☒ headphone	☒ Load compartment cover	☒ LED headlights	☒ navigation system
☒ Persenning	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	Winter tires	aluminum
1st axis - Left / states .	Nokian	235/60/R18/107V 4 mm
1st axis - right / states .	Nokian	235/60/R18/107V 4 mm
2nd axis - Left / states .	Nokian	235/60/R18/107V 4 mm
2nd axis - right / states .	Nokian	235/60/R18/107V 4 mm
traffic Safety:	roadworthy	
spare wheel:	Tirefit	
state spare wheel:	-	

standard equipment	
• 3rd brake light • Airbag switched off • • Anti-Blockier-System (ABS) • <i>Innenspiegel mit Abblendautomatik</i> • Outside mirror electr. adjustable and heated, both • Mirrors Wide • • Indicator LED integrated in the exterior mirror • • Digital Package <i>Service-System: Google Services, Induktionsladeschale für Smartphone</i> • Door sill trims with aluminum inlay • First aid kit / first aid kit • Automatic stability control • Fahrassistenz-System Berganfahr-Assistent (HSA) • Driving Assistance System Driving profile selection (Drive Mode) • Fahrassistenz-System Multikollisionsbremse (Multi Collision Brake) • Electric windows front + rear • Luggage compartment partition (net) • Speed control system (cruise control) • Rear window heatable • Isofix seats for child seat • Keyless Drive • Knee airbag , driver's side • Rear headrests electr. folding •	• Airbag passenger side • Airbag driver side • Trailer stabilization program (TSA) Preparation • Drive Configuration front-wheel drive • Outside mirror electr. anklappbar • Mirrors black , high-gloss • Outside temperature display • Operating tailgate / lids automatically • board computer • Roof rails black , high-gloss • Digital instrumentation 12.3 "display 2nd generation • Elektron. Differentialsperre Corner Traction Control (CTC) mit Torque Vectoring • Fahrassistenz-Paket Safety Assistance <i>Fahrassistenz-System: Verkehrszeichenerkennung (Road Sign Information, RSI), Geschwindigkeits-Begrenzeranlage, Fahrassistenz-System: City-Safety-System (Autonomer Notbrems-Assistent), Fahrassistenz-System: Straßenrand-Erkennung (Road Edge Detection), Fahrassistenz-System: Connected Safety, Fahrassistenz-System: aktiver Spurhalteassistent (LKA), Fahrassistenz-System: Oncoming Lane Mitigation, Fahrassistenz-System: Müdigkeits-Warner (Driver-Alert-Control, DAC), Fahrassistenz-System: Ready to Drive Notification</i> • Driving Assistance System Hill Descent Control (HDC) • Vehicle assistance system emergency braking assistant • Driver assistance system High beam assistant • • Window trim Shiny Black • Luggage compartment cover / shade



• Steering wheel with multifunction • Steering column (steering wheel) longitudinally adjustable • Air Quality Monitoring System (Clean Zone Interior Package CZIP) • Mild-Hybrid 155 kW (Motor 2,0 Ltr. - 145 kW Diesel) • facelift • Rear fog light • • Tire pressure monitoring system • Split rear seat • Low-emission according to the Euro 6d exhaust gas standard • Headlamp LED with adaptive light distribution (Intelligent Light System) • Side airbag in front • • Seat front left electr. adjustable (with memory) • Sports pedals • Start / Stop system • Daytime running light LED • • Warning system for seat belts front and rear • <i>Sitzheizung vorn, Lenkradheizung</i>	• Transmission Automatic - Geartronic (8-step) • rear spoiler • Body 5-door • Keyless Start • Head airbag system • • Steering wheel (sport) • Steering column (steering wheel) height adjustable • LM rims • Illuminated make-up mirror • Front center armrest with cup holders • fog lights LED • Park brake electric • Tire repair kit • Rußpartikelfilter • Rear seat backs foldable • Rain-sensing wipers • Whiplash protection system (WHIPS) • Sensor disc fitting detection • Seat belts front height adjustable • Front seats height adjustable • Sports seats part leather / mesh textile <i>Innenausstattung: Dekoreinlagen Aluminium Metall Mesh, Mittelarmlehne hinten mit Getränkehalter, Seitenwangen elektr. verstellbar Sitze vorn</i> • Socket (12V) port in the trunk / cargo area • Bag hook in the luggage compartment • • immobilizer • Central locking with remote control
---	--

special Features	
• Driver Assistance package <i>Geschwindigkeits-Regelanlage (Tempomat) mit Abstandsregelung und Einleitung der Notbremsung, Fahrassistenz-System: Abstandswarner</i> • Heated front window • Fuel tank 71 liters • Darkened side windows from the B-pillar • Xenium package <i>Schiebe-/Hebedach elektrisch (Glas), Klimaautomatik 4-Zonen, Ionisator zur Luftreinigung (erweiterte Reinigung der Innenraumluft)</i>	• Bluetooth hands-free system including audio streaming • Infotainment-System Android (DAB+) mit High Performance Sound Pro (Harman-Kardon) • Park Assistant Package <i>Rückfahrkamera</i> • Special paint Crystal White Pearl Effect

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	Conducted limited To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.
Mileage plausible:	yes yes
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	- -
reference:	

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			examined limited		
oil loss:			examined limited		
air conditioning:			examined limited	lighting system:	
			examined limited		
coupling:			unavailable	exhaust System:	
			examined limited		
engine running:			examined limited	shock absorber:	
			examined limited		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*

damage



	component	Damage	Rep kind
1.		Missing	Replace
2.	Rear bumper	Wear and tear	acceptable
3.	Door Rear - right	Wear and tear	acceptable
4.	Windshield	Chipping from stones	Replace
5.	Fahrersitz	Wear and tear	acceptable
6.	Door Rear - right	Scratch(es)	

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims




rims




engine compartment



service book



Others



Navigation system



2. Rear bumper



2. Rear bumper



3. Door Rear - right




4. Windshield



5. Fahrersitz



5. Fahrersitz



6. Door Rear - right