

Vehicle details

VIN	YV1XZBBVF L2344829	Brand	VOLVO	Maintenance date	-
Licence Plate	H2-15-XN	Model	XC40 T5 Twin Engine Geartronic Momentum Pro	Maintenance mileage	-
Registration date	19/06/2020	Year	2020	Exterior Color	Black Metallic
Odometer	84 657 km	Engine size	1477	interior Color	Black
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	5	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	24/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Leather	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓
Vehicle charger	✓
Wireless charger	✗

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Continental 235/55/18 Summer 5.0 mm		Continental 235/55/18 Summer 5.5 mm	
Continental 235/55/18 Summer 4.0 mm		Continental 235/55/18 Summer 4.0 mm	

Exterior

2		Part Position Damages Severity Repair mode	Roof - Dented Diameter (mm) > 20 Smart Repair	3		Part Position Damages Severity Repair mode	Bumper Front Scratched Length (cm) > 10 Repair
4		Part Position Damages Severity Repair mode	Spoiler Front left Scratched Length (cm) > 10 Repair	5		Part Position Damages Severity Repair mode	Alloy wheel 18" Front right Scratched - Lumpsum repair
6		Part Position Damages Severity Repair mode	Door Front right Dented Diameter (mm) > 20 Smart Repair	7		Part Position Damages Severity Repair mode	Alloy wheel 18" Back right Scratched - Lumpsum repair
8		Part Position Damages Severity Repair mode	Bumper Back left Scratched Length (cm) > 10 Repair	9		Part Position Damages Severity Repair mode	Door Back left Dent & Chips Diameter (mm) > 20 Repair
10		Part Position Damages Severity Repair mode	Alloy wheel 18" Front left Scratched - Lumpsum repair	11		Part Position Damages Severity Repair mode	Tailgate / Boot door - Dented Diameter (mm) > 20 Smart Repair
12		Part Position Damages Severity Repair mode	Door Front left Scratched Length (cm) > 10 Repair				

Others

1		Part Position Damages Severity Repair mode	Wireless charger - Missing - For info
---	---	--	---