



Hüsges Gruppe®
Die Gutachter

status report

customer: Bank 11, Neuss
contract number: 760667230
reference:

vehicle data

Alfa Romeo Giulietta Sprint

Vehicle identification number	ZAR94000007552311	mileage read:	40645 km
First Registration / construction year:	08.06.2021 / 2019	Visit Date / place of birth:	20.08.2025 Riedstadt-Goddelau
Bodywork:	cars	Re - import:	no
Body type:	hatchback	KBA no. :	1742//AAL
Fuel / emission class:	gasoline / € 6	transmission type:	manual transmission
Displacement / power:	1368 ccm / 88 kW (120 PS)	Engine:	front-wheel drive
paint:	COLORE ESTERNO (Alfa Weiss)	Number of previous owners:	Unbekannt
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	Cloth / Alcantara
Service book available:	yes	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	13749 / 04.08.2022
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle documents:	-	state outside:	3 - Average
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided /	Last service at / on:
Hard Disk Drive	2	maintained:	13749 / 04.08.2022
		yes / -	
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Ein Unternehmen der Hüsges Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsges
Dipl.- Ing. (FH) Bernd Hüsges

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	Winter tires	aluminum
1st axis - Left / states .	Dunlop	225/40/R18/92V 5 mm
1st axis - right / states .	Dunlop	225/40/R18/92V 5 mm
2nd axis - Left / states .	Dunlop	225/40/R18/92V 3 mm
2nd axis - right / states .	Dunlop	225/40/R18/92V 3 mm
traffic Safety:	roadworthy	
spare wheel:	Tirefit	
state spare wheel:	-	

standard equipment	
• • Airbag switched off • Anti- lock braking system (ABS) • Electric wing mirror . adjustable , heated and folding • brake Assist • Dynamic Steering Torque (DST) • Electron. Differential lock (Q2) • Driving Assistance System Hill Start Assist (Hill Holder) • Electric windows front • • Transmission 6-speed • LED Taillights • UConnect infotainment system with CD and MP3 player, navigation system and DAB radio reception • • Body 5-door • Head airbag system • Cornering Brake Control (CBC) • Steering wheel (sports/leather, flattened at the bottom, red seams) • Steering column (steering wheel) adjustable (vertical / axial) • Rear center armrest • • Multi -function display • Pastel painting • Rear seat split / folding • Shift / selector lever handle in leather • side airbags •	• Adaptive Cruise Control • Airbag Driver / passenger side • Acceleration skid control (ASR) • Brembo braking system • Headlining black • Electron. Brake force distribution • Driving Assistance System Alfa Romeo DNA Dynamic Handling System • Power windows Rear • Window frame black • Doormats • • Body color rear spoiler • • Isofix admissions for child seat • 2-zone automatic climate control • Rear headrests (3- fold) • Lumbar support seat front left and right, electr. adjustable • Steering wheel with paddles / buttons • LM rims • Front center armrest • Motor 1,4 Ltr. - 88 kW Turbo KAT • Fog lights with glossy black frame • aluminum pedals • Low-emission according to the Euro 6d-TEMP emissions standard • • Darkened rear side windows and rear windscreen • Power Steering (Active Steering) • Front right seat adjustable (6-way)

• Front left adjustable (6-fold) • Seat relation / upholstery Alcantara / fabric • Start / Stop system • Front and rear bumpers with red decorative stripes • • Wärmeschutzverglasung	• Heated front seats • Socket (12V connection) in the center console • LED daytime running lights • Door handles outside black • Central locking with remote control
--	--

special Features	
• Comfort Package <i>Außenspiegel elektr. anklappbar, Licht- und Regensensor, Einparkhilfe elektronisch vorn und hinten, Mittelarmlehne hinten, Innenspiegel mit Abblendautomatik</i>	

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed.
Mileage plausible:	not testable not testable Wartung fällig
reference:	
Note Road Safe:	Abblendlicht Rechts ohne Funktion

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	Not established On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

Overview conducted technology audit

Alternator / Generator:	✓ examined limited	Battery / accumulator:	✓ in order
oil loss:	✓ examined limited		
air conditioning:	✓ examined limited	lighting system:	✓ examined limited
coupling:	✓ examined limited	exhaust System:	✓ examined limited
engine running:	✓ examined limited	shock absorber:	✓ examined limited
transmission:	✓ examined limited		

Performed testing technology

Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The clutch could be tested only limited within the test drive / pull test .
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen.

damage



component	Damage	Rep kind
1. maintenance	Due	Replace
2. Polster Fußraum VL	Damaged	Replace
3. Rim front - left	Damaged	Replace
4. Rim rear - left	Damaged	Replace
5. Rim rear - right	Damaged	Replace
6. Rim front - right	Damaged	Replace
7. Tire-fit filler	Missing	Replace
8. Beide Reifen Vorne	Worn	Replace
9. Front bumper	Scrape	Paint
10. Türeinstieg Vorne - Links	Damaged	Refurbish and paint
11. Front door - left	Scratch(es)	Smart repair
12. Rear door - left	Scratch(es)	Smart repair
13. Sitzreihe Hinten	Dirty	
14. Rear door trim - left	Damaged	Smart repair
15. tailgate trim	Wear and tear	acceptable
16. Rear bumper	Scratch(es)	Paint
17. Sidewall - Rear - right	Deformed	Refurbish and paint
18. Roof frame - right	Damaged	Refurbish and paint
19. Door Rear - right	Deformed	Refurbish and paint
20. Abblendlicht Rechts	No functionality	Carry out a fault diagnosis
21. silencer	Damaged	Replace
22. Stoßfänger Hinten Unterer Teil	Damaged	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



2. Polster Fußraum VL



3. Rim front - left



3. Rim front - left



4. Rim rear - left



4. Rim rear - left



5. Rim rear - right



5. Rim rear - right



5. Rim rear - right



6. Rim front - right



6. Rim front - right



8. Beide Reifen Vorne



8. Beide Reifen Vorne



9. Front bumper



9. Front bumper



10. Türeinstieg Vorne - Links



10. Türeinstieg Vorne - Links



11. Front door - left



12. Rear door - left



13. Sitzreihe Hinten



13. Sitzreihe Hinten



14. Rear door trim - left



15. tailgate trim



16. Rear bumper



16. Rear bumper




17. Sidewall - Rear - right



17. Sidewall - Rear - right



17. Sidewall - Rear - right



18. Roof frame - right



18. Roof frame - right



19. Door Rear - right



19. Door Rear - right



20. Abblendlicht Rechts



21. silencer



22. Stoßfänger Hinten Unterer Teil



22. Stoßfänger Hinten Unterer Teil