

# ALFA ROMEO TONALE Tonale 1.5 Hybrid 160 ch VGT TCT7 Edizione Speciale

**BCA** 

VIN NO ZARNASSA5N3023175 Registration Number GN113KY

**Number of Owners** 

MOT Date

•••

Number of Keys

**Odometer Reading** 

₩-

**:::**-

**P**1

**18000 km** 

Last Service

Last Service Mileage

First Registration Date

Country First Registered

**#**-

**?** -

2023-04-19

8

## **Inspection Report Summary**

| Customer                | BCAuto Encheres               | Report Number  | P20250801002254 |
|-------------------------|-------------------------------|----------------|-----------------|
| Inspection Date / Place | 2025-07-31 / BCA<br>INGRANDES | Cosmetic Grade | 1               |

### Vehicle Summary

| Vehicle Condition | Runner                | VAT Type           | Exempt Rate |
|-------------------|-----------------------|--------------------|-------------|
| Fuel Type         | Petrol                | Gearbox Type       | Auto clutch |
| Colour            | Blue                  | Engine Size (cc)   | 1469        |
| Engine Size       | 1.5                   | No of Doors        | 5           |
| Body Type         | Stationwagon / Estate | Drive Train        | Front       |
| Seat Colour       |                       | No of Seats        | 5           |
| Charging Cables   |                       | WLTP CO2 Emissions |             |

## Vehicle History & Documents

| Service Book Available | Present    | Next Service Mileage | km |
|------------------------|------------|----------------------|----|
| Previous Usage         | Normal Use | Imported             | No |
| Manufacturer Warrenty  |            |                      |    |























# Equipment


| Central locking         | Rear parking sensors | Electric Tailgate | Cruise control    |
|-------------------------|----------------------|-------------------|-------------------|
| Satellite navigation    | Radio                | Alloys wheels     | Stability control |
| Power assisted steering |                      |                   |                   |
| Equipment Details       |                      |                   |                   |

| Seat Heating | No | Air Conditioning | Yes |  |
|--------------|----|------------------|-----|--|
|--------------|----|------------------|-----|--|

# Wheels & Tyres

| Left Rear Tyre Depth  | 4 | Left Front Tyre Depth  | 4 |
|-----------------------|---|------------------------|---|
| Right Rear Tyre Depth | 4 | Right Front Tyre Depth | 4 |

## Cosmetic Damage



|   | Component         | Damage                    | Comments |
|---|-------------------|---------------------------|----------|
| 1 | Rim / Front Left  | Paint / Chipping          |          |
| 2 | Rim / Front Right | Out of Bodywork / Scratch |          |
| 3 | Rim / Back Right  | Out of Bodywork / Scratch |          |



1. Rim / Front Left Paint / Chipping -

2. Rim / Front Right Out of Bodywork / Scratch -



3. Rim / Back Right Out of Bodywork / Scratch -

## **Mechanical Condition**

| Levels  |          |   |          |
|---|----------|---|----------|
| Coolant Fluid - Condition                       | •        | Oil - Condition   | •        |
| Level - Oil                                     | <b>②</b> | Coolant Fluid   | •        |
| Brakes Fluid                                    | •        |   |          |
| Dashboard Lights                                |          |   |          |
| ABS Warning Light                               | <b>⊘</b> | Diesel Particulate Filter Light   | •        |
| ESP Fault/Traction Control<br>Malfunction Light | •        | 4WD Light   | •        |
| Dashboard Working                               | •        | Oil Pressure Warning Light  | •        |
| Engine Light                                    | •        | Airbag Warning Light  | •        |
| Brake Warning Light                             | •        | Level - Fuel / Battery  | 10       |
| Transmission Warning Light                      | •        | Steering Fluid Level  | <b>②</b> |
| Service Light                                   |          |   |          |
| Equipments Test                                 |          |   |          |
| Electric Windows                                | •        | Convertible, Sunroof, Wagon,<br>Flatbed truck, Tailgate<br>electrics test | •        |
| Dump / Trail / Tail Gate Lift                   | NA       | Main & Spare Keys<br>Functioning  | •        |
| Central Locking                                 | •        | Audio Equipment   | •        |
| Navigation System                               | •        | AC / Heating System   | <b>②</b> |
| Parking Sensors / Cameras<br>Functioning        | <b>⊘</b> |   |          |
| Hybrid/EV                                       |          |   |          |
| Charge Port Condition                           | •        | Charge lead 1 condition<br>/Charge lead 2 condition                       | NA       |
| Hybrid System Fault                             | NA       |   |          |
| Engine  |          |   |          |
| Cross Member                                    | <b>⊘</b> | Serpentine Belt   | <b>⊘</b> |
| Control Liquid Leak                             | •        |   |          |
| Comments  |          |   |          |

#### Comments

Batterie HS / Frein de parking à contrôler / ESC à contrôler / direction assistée à contrôler / pas de puissance

#### **Tyres**

Presence Anti-Theft Lock Nut 📀

## **Test Drive Inspection**

| Test Drive  |          |                                     |          |  |
|---|----------|-------------------------------------|----------|--|
| Engine functioning  | •        | Engine / Aux Belt / Pulley<br>Noise | <b>②</b> |  |
| Vehicle Starts  |          | Steering Noise/Gripping             | •        |  |
| Smoke Quantity  | <b>⊘</b> | Transmission                        | •        |  |
| Clutch Functioning  | <b>⊘</b> | Steering                            |          |  |
| Brakes Functionning   | •        | Engine Power                        |          |  |
| <ul> <li>No troubles detected, good condition or correct tests, according to vehicle age and mileage</li> <li>Damages or malfunction detected that requires repairs by the buyer</li> <li>Not applicable</li> <li>Not tested</li> </ul> |          |                                     |          |  |

#### **Disclaimer Section**

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.