



IVECO DAILY
DAILY BP FGN 35 C 14S EMP 3520L V12
H2 Q-TOR BVM6

VIN NO ZCFCL35A305558010
Registration Number GP376RD



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



2023-06-20

Odometer Reading



28028 km

Country First Registered



France

Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20250513164336
Inspection Date / Place	2025-05-13 / BCA ROPPE	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Not Movable	VAT Type	Qualified - Normal Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour		Engine Size (cc)	2287
Engine Size	2.3	No of Doors	5
Body Type	Box Wagon	Drive Train	Rear
Seat Colour		No of Seats	3
Seat Covering Name		Seat Covering	Cloth
Charging Cables		WLTP CO2 Emissions	

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage	Normal Use	Imported	
Manufacturer Warrenty			





Equipment


Central locking	Cruise control	Radio	Power assisted steering
-----------------	----------------	-------	-------------------------

Equipment Details


Air Conditioning	No
------------------	----

Cosmetic Damage

14 Dommages



10 Dommages



Component		Damage	Comments
1	Panel Filling / Front Left	Interior / Scraped	
2	Panel Filling / Front Left	Interior / Dirty	
3	Floor Carpet	Interior / Dirty	
4	Seat Cushion / Front Left	Interior / Dirty	
5	Roof Upholstery	Interior / Distorted	
6	Trunk Carpet	Interior / Dirty	
7	Panel Filling / Front Right	Interior / Scraped	
8	Panel Filling / Front Right	Interior / Dirty	
9	Seat / Front Right	Interior / Dirty	
10	Dashboard / Front	Interior / Scraped	
11	Cant Rail / Right	Bodywork / Breakage	
12	Mirror / Front Left	Paint / Scratch / Line	
13	Cant Rail / Right	Bodywork / Dent / Deformation	

14	Corner Bumper / Back Left	Bodywork / Breakage / Hole
15	Corner Bumper / Back Left	Paint / Scratch / Line
16	Back Light / Left	Glass Break
17	Bumper / Back	Bodywork / Dent / Deformation
18	Side Panel / Back Right	Bodywork / Dent / Deformation
19	Side Panel / Back Right	Bodywork / Dent / Deformation
20	Door / Back Right	Bodywork / Dent / Deformation
21	Cant Rail / Right	Bodywork / Dent / Deformation
22	Cant Rail / Right	Bodywork / Breakage
23	Mirror / Front Right	Paint / Scratch / Line
24	Fender / Front Right	Paint / Scratch / Line



1. Panel Filling / Front Left
Interior / Scraped -



2. Panel Filling / Front Left
Interior / Dirty -



3. Floor Carpet
Interior / Dirty -



4. Seat Cushion / Front Left
Interior / Dirty -



5. Roof Upholstery
Interior / Distorted -



6. Trunk Carpet
Interior / Dirty -



7. Panel Filling / Front Right Interior / Scraped -



8. Panel Filling / Front Right Interior / Dirty -



9. Seat / Front Right Interior / Dirty -




10. Dashboard / Front Interior / Scraped -



11. Cant Rail / Right Bodywork / Breakage -



12. Mirror / Front Left Paint / Scratch / Line -



13. Cant Rail / Right
Bodywork / Dent / Deformation -



14. Corner Bumper / Back Left
Bodywork / Breakage / Hole -



15. Corner Bumper / Back Left
Paint / Scratch / Line -



16. Back Light / Left
Glass Break -



17. Bumper / Back
Bodywork / Dent / Deformation -



18. Side Panel / Back Right
Bodywork / Dent / Deformation -



19. Side Panel / Back Right
Bodywork / Dent / Deformation -



20. Door / Back Right
Bodywork / Dent / Deformation -



21. Cant Rail / Right
Bodywork / Dent / Deformation -



22. Cant Rail / Right
Bodywork / Breakage -



23. Mirror / Front Right
Paint / Scratch / Line -



24. Fender / Front Right
Paint / Scratch / Line -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.