

Vehicle details

VIN	ZFA263000 06T17241	Brand	FIAT	Maintenance date	-
Licence Plate	W67155K	Model	DOBLO Kasten L2H1 1,6 Multijet II 105 Lounge 7	Maintenance mileage	-
Registration date	30/11/2020	Year	1000	Exterior Color	White Solid
Odometer	15 431 km	Engine size	1598	interior Color	Black
Fuel	Diesel	Body Type	Panel van	Next technical inspection	01/11/2025
Seats	-	Transmission	Manual	CO2	-
Doors	4	Gears	-		

Inspection Details

Inspection date	26/05/2025	Inspection loc.	Hödlmayr Logistics GmbH
-----------------	------------	-----------------	-------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
GPS system	✓
Front radars	✓
Reversing radars	✓
Reversing camera	✓

Removable element

--	--

Technical Document


User manual	✓
Log books	✓
Spare key	✓
Remote key	✓

Tyres

Winter kit

Michelin 195/60/16 T Winter 4.2 mm		Michelin 195/60/16 T Winter 4.3 mm	
Michelin 195/60/16 T Winter 4.0 mm		Michelin 195/60/16 T Winter 4.0 mm	

Exterior

1		Part	Windscreen	2		Part	Bonnet
		Position	-			Position	-
		Damages	Stone impact			Damages	Dent & Chips
		Severity	-			Severity	-
		Repair mode	For info			Repair mode	Repair

3



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	For info

4



Part	Wing
Position	Front left
Damages	Dent & Chips
Severity	-
Repair mode	Replace

5



Part	Door
Position	Front left
Damages	Scratched
Severity	-
Repair mode	For info

6



Part	Door sill
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Repair

7



Part	Side panel
Position	Back left
Damages	Dented
Severity	-
Repair mode	For info

8



Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	For info

9



Part	Door
Position	Back left
Damages	Dented
Severity	-
Repair mode	For info

10




Part	Door
Position	Back right
Damages	Dented
Severity	-
Repair mode	For info

11



Part	Side panel
Position	Back right
Damages	Dented
Severity	-
Repair mode	For info

12



Part	Door
Position	Front right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

13



Part	Roof
Position	-
Damages	Dented
Severity	-
Repair mode	Repair

Others

14



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Paintworks