

FIAT 500 500 0.9 TwinAir Start&Stopp



VIN NO ZFA31200000877920 Registration Number 0000877920

MOT Date

Number of Owners

Odometer Reading

₩-

4 Last Service

22

128767 km

2019-12-27

Last Service Mileage

First Registration Date

Number of Keys

Country First Registered

86182

2012-09-12

=-

Inspection Report Summary

| Customer | BCA Online | Report Number | P20251001132930 |
|-------------------------|---------------------|----------------|-----------------|
| Inspection Date / Place | 2025-10-01 / Extern | Cosmetic Grade | 4 |

Vehicle Summary

| Vehicle Condition | Runner | VAT Type | Margin |
|--------------------|--------|------------------------|--------|
| Fuel Type | Petrol | Road Worthy | Yes |
| Colour | Black | Engine Size (cc) | 875 |
| Engine Size | 0.9 | No of Doors | 3 |
| Body Type | Sedan | Drive Train | Front |
| Seat Colour | | No of Seats | 4 |
| Seat Covering Name | Grau | Seat Covering | Cloth |
| Charging Cables | | NEDC CO2 Rating (q/km) | 92 |
| Gearbox Type | Manual | | |

Vehicle History & Documents

| Service Book Available | Present | Next Service Mileage | km |
|------------------------|---------|----------------------|----|
| Previous Usage | | Imported | No |
| Manufacturer Warrenty | | | |


























Equipment


| Airbag Status | Anti-lock braking | Front fog lamps | Remote central locking |
|-------------------|-------------------------------|--------------------------|------------------------|
| Stability control | CD Player | Radio | Alloys wheels |
| Auxiliary Socket | Remote adjusting wing mirrors | Split folding rear seats | Sunroof |
| | | | |

Leather steering wheel

Equipment Details

| Air Conditioning | Yes | Alloy Wheel Size | 16 |
|-----------------------|-----------------|------------------------|----|
| Sunroof Type | Fixed Panoramic | | |
| Wheels & Tyres | | | |
| Left Rear Tyre Depth | 5 | Right Rear Tyre Depth | 5 |
| Left Front Tyre Depth | 6 | Right Front Tyre Depth | 6 |

Cosmetic Damage



| | Component | Damage | Comments |
|----|-------------------------|-------------------------------|----------|
| 1 | Rim / Front Left | Out of Bodywork / Scratch | |
| 2 | Fender / Back Left | Paint / Scratch / Scuff | |
| 3 | Rim / Back Left | Out of Bodywork / Scratch | |
| 4 | Side Panel / Back Left | Paint / Scratch / Scuff | |
| 5 | Side Panel / Back Left | Bodywork / Dent / Deformation | |
| 6 | Bumper / Back | Paint / Scratch / Scuff | |
| 7 | Tailgate | Bodywork / Dent / Deformation | |
| 8 | Rim / Back Right | Out of Bodywork / Scratch | |
| 9 | Fender / Back Right | Bodywork / Dent / Deformation | |
| 10 | Rim / Front Right | Out of Bodywork / Scratch | |
| 11 | Bumper / Front | Paint / Scratch / Scuff | |
| 12 | Side Panel / Back Right | Bodywork / Dent / Deformation | |

| 13 | Door / Front Right | Bodywork / Dent / Deformation |
|----|---------------------|-------------------------------|
| 14 | Door / Front Right | Bodywork / Dent / Deformation |
| 15 | Roof | Bodywork / Dent / Deformation |
| 16 | Fender / Back Left | Bodywork / Dent / Deformation |
| 17 | Fender / Front Left | Bodywork / Dent / Deformation |
| 18 | Roof Upholstery | Interior / Non - compliant |




1. Rim / Front Left
Out of Bodywork / Scratch -

2. Fender / Back Left Paint / Scratch / Scuff -



3. Rim / Back Left Out of Bodywork / Scratch -

4. Side Panel / Back Left Paint / Scratch / Scuff -



5. Side Panel / Back Left Bodywork / Dent / Deformation -

6. Bumper / Back Paint / Scratch / Scuff -



7. Tailgate Bodywork / Dent / Deformation -

8. Rim / Back Right
Out of Bodywork / Scratch -




9. Fender / Back Right Bodywork / Dent / Deformation -

10. Rim / Front Right
Out of Bodywork / Scratch -




11. Bumper / Front Paint / Scratch / Scuff -

12. Side Panel / Back Right Bodywork / Dent / Deformation -




13. Door / Front Right Bodywork / Dent / Deformation -

14. Door / Front Right Bodywork / Dent / Deformation -



15. Roof Bodywork / Dent / Deformation -

16. Fender / Back Left Bodywork / Dent / Deformation -



17. Fender / Front Left Bodywork / Dent / Deformation -

18. Roof Upholstery Interior / Non - compliant -

Mechanical Condition

| Equipments Test | | | |
|----------------------------------|----------|---|----------|
| Central Locking | ⊘ | Electric Windows | • |
| Audio Equipment | ⊘ | AC / Heating System | • |
| Main & Spare Keys Functioning | | Other Equipments | • |
| Control Lights | | | |
| ABS Warning Light | • | ESP Fault/Traction Control Malfunction Light | ② |
| Airbag Warning Light | • | Oil Pressure Warning Light | • |
| Brake Warning Light | • | Power Steering Warning Light | • |
| Alternator / Battery | ② | No Dashboard Lights | • |
| Service Light | ⊘ | Display Defect | ⊘ |
| Engine | | | |
| Engine Status / EML | ⊘ | Engine Leak Visible | • |
| Engine Starts | ⊘ | | |
| Levels | | | |
| Brakes Fluid | ② | Coolant Fluid | ② |

Test Drive Inspection

description.

Steering Wheel Steering | Noise / Anomaly **Engine** The Gears Scratch / Skip / **Engine Noise Abnormal Operation Fume Quantity Power Loss Brake Brake System Anomaly** Clutch **Clutch Functioning** General **Test Driven Status** No troubles detected, good condition or correct tests, according to vehicle age and mileage Damages or malfunction detected that requires repairs by the buyer NA Not applicable ■ Not tested Disclaimer Please also note the "UserGuide condition report", which shows the scope of the vehicle

User Guide