

FIAT 500 Benzina 500 1.2 S 69cv E6

VIN NO ZFA3120000J111656 Registration Number ET212HL



MOT Date

A 2023-10-20

Last Service

#-

Number of Owners

:2:-

Last Service Mileage

23-

Number of Keys

P

First Registration Date

2013-11-29

Odometer Reading

149640 km

Country First Registered

Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20250925171018
Inspection Date / Place	2025-09-25 / BCA Lodi	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Gearbox Type	Automatic
Colour	Black	Engine Size (cc)	1242
Engine Size	1.2	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour	Black	No of Seats	4
Seat Covering Name		Seat Covering	Leather
Charging Cables		NEDC CO2 Rating (q/km)	119

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			































Equipment


Central locking	Alloys wheels	Volante multifuncion	Remote adjusting wing mirrors
Trip Computer	Stability control	Power assisted steering	Digital Radio
Parcel Shef	Remote central locking	Tyre Mobility Kit	

Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Winter	
	PIRELLI	195/45//R16 - 84H / 1 mm
	PIRELLI	195/45//R16 - 84H / 1 mm
	PIRELLI	195/45//R16 - 84H / 2 mm
	PIRELLI	195/45//R16 - 84H / 2 mm

Cosmetic Damage



	Component	Damage	Comments
1	Aeration Grid / Front Center	Interior / Broken	
2	Dashboard / Front	Interior / Scratched	
3	Panel Filling / Front Left	Interior / Scratched	
4	Seat / Front Left	Interior / Worn - out	
5	Rim / Front Left	Out of Bodywork / Scratch	
6	Tire / Front Left	Tire	
7	Door / Front Left	Bodywork / Dent	
8	Rim / Back Left	Out of Bodywork / Scratch	
9	Fender / Back Left	Paint / Scratch / Line	
10	Bumper / Back	Paint / Scratch / Line	
11	Fender / Back Right	Bodywork / Dent	
12	Rim Brake pads	Out of Bodywork / Scratch	

13	Door / Front Right	Paint / Scratch / Line
14	Door / Front Right	Bodywork / Dent
15	Rim / Front Right	Out of Bodywork / Scratch
16	Hood	Paint / Chipping
17	Windshield / Front	Glass Break / Impact
18	Roof	Bodywork / Dent



1. Aeration Grid / Front Center Interior / Broken -

2. Dashboard / Front Interior / Scratched -




3. Panel Filling / Front Left Interior / Scratched -

4. Seat / Front Left Interior / Worn - out -



5. Rim / Front Left Out of Bodywork / Scratch -

6. Tire / Front Left Tire - Replace



7. Door / Front Left Bodywork / Dent -

8. Rim / Back Left Out of Bodywork / Scratch -



9. Fender / Back Left Paint / Scratch / Line -



10. Bumper / Back Paint / Scratch / Line -



11. Fender / Back Right Bodywork / Dent -



12. Rim Brake pads Out of Bodywork / Scratch -



13. Door / Front Right Paint / Scratch / Line -

14. Door / Front Right Bodywork / Dent -



15. Rim / Front Right Out of Bodywork / Scratch -

16. Hood Paint / Chipping -



17. Windshield / Front Glass Break / Impact -

18. Roof Bodywork / Dent -

Mechanical Condition

Engine					
Engine Starts	•	Vehicle Start - up	•		
Engine Leak Visible	•				
Clutch					
Clutch Functioning	(1)				
Equipments Test					
Other Equipments	•	AC / Heating System	•		
Levels					
Brakes Fluid	•	Coolant Fluid	•		
Test Drive Inspection					
Other Checks					
Steering	•	Brakes	•		
Suspension					
Gearbox					
Manual Gearbox	•				
General					
Test Driven Status	•				
Equipments Test					
Steering Noise / Anomaly	•				
Engine					
Power Loss	•	Fume Quantity	•		
Engine Noise	•				
 No troubles detected, good condition or correct tests, according to vehicle age and mileage Damages or malfunction detected that requires repairs by the buyer Not applicable Not tested 					