



FIAT Panda III 2021

Panda 1.0 firefly hybrid City Life s&s 70cv

VIN NO ZFABF5CJ5N3J06773
Registration Number 3J06773



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	-	-	47428 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2023-02-13	Spain

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20250926123505
Inspection Date / Place	2025-09-26 / BCA Lodi	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualified
Fuel Type	Hybrid	Gearbox Type	Manual
Colour	Black	Engine Size (cc)	999
Engine Size	1.0	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour	Black	No of Seats	4
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	89

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Rental Car	Imported	Yes
Manufacturer Warrenty			





Equipment

Central locking	Digital Radio	Remote central locking	Tyre Mobility Kit
Power assisted steering	Parcel Shef	Trip Computer	Stability control


Wheels & Tyres

Mounted Tires

Tyre / Wheel Type	Summer	
	GOODYEAR GOODYEAR-EFFICIENTGRIP PERFORMANCE	185/55//R15 - 82H / 3 mm
	GOODYEAR GOODYEAR-EFFICIENTGRIP PERFORMANCE	185/55//R15 - 82H / 3 mm
	GOODYEAR GOODYEAR-EFFICIENTGRIP PERFORMANCE	185/55//R15 - 82H / 3 mm
	GOODYEAR GOODYEAR-EFFICIENTGRIP PERFORMANCE	185/55//R15 - 82H / 3 mm

Cosmetic Damage

20 Danni




0 Danni



Component		Damage	Comments
1	Windshield / Front	Glass Break / Impact	
2	Hood	Bodywork / Dent / Hail Area	
3	Bumper / Front	Bodywork / Dent	
4	Fender / Front Left	Bodywork / Dent	
5	Mirror Shell / Front Left	Paint / Scratch / Line	
6	Door / Front Left	Bodywork / Poor Previous Repair	
7	Door / Back Left	Bodywork / Poor Previous Repair	
8	Fender / Back Left	Paint / Scratch / Line	
9	Bumper / Back	Paint / Scratch / Line	
10	Tailgate	Bodywork / Dent	
11	Fender / Back Right	Paint / Scratch / Line	
12	Fender / Back Right	Bodywork / Dent	

13	Door / Back Right	Bodywork / Dent
14	Door / Front Right	Bodywork / Dent
15	Mirror Shell / Front Right	Paint / Scratch / Line
16	Fender / Front Right	Bodywork / Dent
17	Pillar / Front Right	Bodywork / Dent
18	Roof	Bodywork / Dent / Hail Area
19	Roof	Bodywork / Dent
20	Pillar / Front Left	Bodywork / Dent / Hail Area



1. Windshield / Front
Glass Break / Impact -




2. Hood
Bodywork / Dent / Hail Area -



3. Bumper / Front
Bodywork / Dent -




4. Fender / Front Left
Bodywork / Dent -



5. Mirror Shell / Front Left
Paint / Scratch / Line -



6. Door / Front Left
Bodywork / Poor Previous Repair -




7. Door / Back Left
Bodywork / Poor Previous Repair -




8. Fender / Back Left
Paint / Scratch / Line -



9. Bumper / Back
Paint / Scratch / Line -



10. Tailgate
Bodywork / Dent -



11. Fender / Back Right
Paint / Scratch / Line -




12. Fender / Back Right
Bodywork / Dent -




13. Door / Back Right
Bodywork / Dent -



14. Door / Front Right
Bodywork / Dent -



15. Mirror Shell / Front Right
Paint / Scratch / Line -



16. Fender / Front Right
Bodywork / Dent -



17. Pillar / Front Right
Bodywork / Dent -



18. Roof
Bodywork / Dent / Hail Area -



19. Roof
Bodywork / Dent -



20. Pillar / Front Left
Bodywork / Dent / Hail Area -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	✓		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	✓

Test Drive Inspection

Other Checks			
Brakes	✓	Steering	✓
Suspension	✓		
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	✓
Engine Noise	✓		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓		

✓ **No troubles detected, good condition or correct tests, according to vehicle age and mileage**

! **Damages or malfunction detected that requires repairs by the buyer**

NA **Not applicable**

☐ **Not tested**