



Fiat Talento: VNG39P

Vinnumber:	ZFAFFL006M5176657	Versionname:	Talento 2.0 MJ 107kW Pro L2H1 GB
First Registrationdate:	19/11/2021	Fiscalpower:	
Expertise Mileage:	198013	Power Kw:	107
Bodytype:		Body colour:	Wit pastel
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Type of rims (mounted):	Steel
Fueltype:	Diesel	Parking lot:	954
Number of seats:	3		
Type of rims (mounted):	Steel		
Maintenance needed:	Yes		

Options

Number of keys total	2	Telephone equipment
GPS		Central consol F
Manual climate control		Rear parking sensors
Windows electric F		Hook
Radio multimedia		Roof rack
		Sliding door right-side

Degree of wear

205/65/16/107 T				
Winter tyres:	Fr.L.	Vredestein: 2,4 mm	Fr.R.	Vredestein: 7,7 mm
	Re.L.	Vredestein: 2,7 mm	Re.R.	Vredestein: 6,2 mm
Tyre profile depth FL				2.4
Tyre profile depth FR				7.7
Tyre profile depth RL				2.7
Tyre profile depth RR				6.2
Tyre size FL				205/65 R 16 107 T
Tyre size FR				205/65 R 16 107 T
Tyre size RL				205/65 R 16 107 T
Tyre size RR				205/65 R 16 107 T
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Service, Maintenance, Execute



Side wall FL (LCV), Dent(s), Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)



Side wall RL, Dent(s), Repair and paint (complete)



Headlight R, Scratch(es), Replace



Bumper FM, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Smart repair



Windscreen, Stone chip(s), Windscreen repair



Side wall RR, Dent(s), Repair and paint (complete)



Sliding door R, Scratch(es), Repair and paint (complete)



Central pillar R, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror glass R, Broken, Replace



Door FR, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Broken, Replace



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)



Side wall panel FR, Broken, Replace



Partition wall, Deformed / Strained, Replace

Partition wall, Deformed / Strained, Replace



Wheel aperture RR, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Smart repair



Boot door panel RL, Dent(s) and scratch(es), Repair and paint (complete)



Boot door panel RR, Dent(s) and scratch(es), Repair and paint (complete)



Supplementary brake light, Broken, Replace



Bumper corner RR, Scratch(es), Repair and paint (complete)



Roof, Dent(s), Repair and paint (complete)



Aerial, Broken, Replace



Air vent R, Broken, Replace

