



LANCIA Musa 2007 Benzina musa 1.4 8v Oro ecochic Gpl

VIN NO ZLA35000001206095
Registration Number EF961LM



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-01-27	-	-	169200 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2011-01-27	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20251010113440
Inspection Date / Place	2025-10-10 / BCA Lodi	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	LPG	Gearbox Type	Manual
Colour	Black	Engine Size (cc)	1368
Engine Size	1.4	No of Doors	5
Body Type	MPV	Drive Train	Front
Seat Colour	Brown	No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	146

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment

Central locking	Alloys wheels	Parcel Shef	Remote central locking
Stability control	Power assisted steering	Digital Radio	Remote adjusting wing mirrors
Trip Computer			


Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Winter
	195/60//R15 - 88T / 4 mm
	195/60//R15 - 88T / 4 mm
	195/60//R15 - 88T / 3 mm
	195/60//R15 - 88T / 3 mm

Cosmetic Damage

34 Danni



6 Danni



Component		Damage	Comments
1	Windshield / Front	Glass Break	
2	Roof	Bodywork / Dent / Hail Area	
3	Hood	Bodywork / Dent / Hail Area	
4	Hood	Bodywork / Dent / Hail Area	
5	Panel Filling / Back Right	Interior / Scratched	
6	Hood	Bodywork / Breakage	LEVA ROTTA NON SI APRE
7	Bumper / Back	Bodywork / Breakage	
8	Door / Front Left	Bodywork / Dent	
9	Rocker Panel / Center Right	Bodywork / Dent	
10	Pillar / Front Left	Bodywork / Dent / Hail Area	
11	Door / Back Left	Bodywork / Dent	
12	Door / Back Right	Bodywork / Dent	

13	Rim / Front Left	Out of Bodywork / Scratch
14	Center Console	Interior / Broken
15	Pillar / Front Right	Bodywork / Dent / Hail Area
16	Fender / Back Left	Bodywork / Dent
17	Seat / Front Right	Interior / Scratched
18	Bumper / Front	Bodywork / Breakage
19	Mirror Shell / Front Left	Bodywork / Breakage
20	Fender / Front Left	Bodywork / Dent / Hail Area
21	Tailgate	Bodywork / Dent / Hail Area
22	Grille / Front	Bodywork / Breakage
23	Shield Grid / Front Center	Bodywork / Breakage
24	Mirror Glass / Front Left	Bodywork / Breakage
25	Rocker Panel / Center Left	Bodywork / Dent
26	HandBrake Handle	Interior / Worn - out
27	Sun Visor / Front Left	Interior / Broken
28	Door / Front Right	Bodywork / Dent
29	Fender / Back Right	Bodywork / Dent
30	Rim / Back Left	Out of Bodywork / Scratch
31	Rim / Front Right	Out of Bodywork / Scratch
32	Panel Filling / Back Left	Interior / Broken
33	Fender / Front Right	Bodywork / Dent
34	Rim / Back Right	Out of Bodywork / Scratch
35	Trunk Stick	Bodywork / Breakage
36	Trunk Stick	Bodywork / Breakage
37	Shield Grid / Front Center	Missing Part
38	Rim Brand Logo / Front Left	Missing Part
39	Rim Brand Logo / Back Right	Missing Part
40	Rim Brand Logo / Front Right	Missing Part




1. Windshield / Front
Glass Break -




2. Roof
Bodywork / Dent / Hail Area -




3. Hood
Bodywork / Dent / Hail Area -



4. Hood
Bodywork / Dent / Hail Area -




5. Panel Filling / Back Right
Interior / Scratched -




6. Hood
Bodywork / Breakage -
LEVA ROTTA NON SI APRE



7. Bumper / Back
Bodywork / Breakage -




8. Door / Front Left
Bodywork / Dent -



9. Rocker Panel / Center Right
Bodywork / Dent -



10. Pillar / Front Left
Bodywork / Dent / Hail Area -



11. Door / Back Left
Bodywork / Dent -



12. Door / Back Right
Bodywork / Dent -



13. Rim / Front Left
Out of Bodywork / Scratch -



14. Center Console
Interior / Broken -



15. Pillar / Front Right
Bodywork / Dent / Hail Area -



16. Fender / Back Left
Bodywork / Dent -



17. Seat / Front Right
Interior / Scratched -



18. Bumper / Front
Bodywork / Breakage -



19. Mirror Shell / Front Left
Bodywork / Breakage -



20. Fender / Front Left
Bodywork / Dent / Hail Area -



21. Tailgate
Bodywork / Dent / Hail Area -




22. Grille / Front
Bodywork / Breakage -



23. Shield Grid / Front Center
Bodywork / Breakage -



24. Mirror Glass / Front Left
Bodywork / Breakage -



25. Rocker Panel / Center Left
Bodywork / Dent -



26. HandBrake Handle
Interior / Worn - out -



27. Sun Visor / Front Left
Interior / Broken -



28. Door / Front Right
Bodywork / Dent -



29. Fender / Back Right
Bodywork / Dent -



30. Rim / Back Left
Out of Bodywork / Scratch -



31. Rim / Front Right
Out of Bodywork / Scratch -



32. Panel Filling / Back Left
Interior / Broken -



33. Fender / Front Right
Bodywork / Dent -



34. Rim / Back Right
Out of Bodywork / Scratch -



35. Trunk Stick
Bodywork / Breakage -



36. Trunk Stick
Bodywork / Breakage -



37. Shield Grid / Front Center
Missing Part -



38. Rim Brand Logo / Front Left
Missing Part -



39. Rim Brand Logo / Back Right
Missing Part -



40. Rim Brand Logo / Front Right
Missing Part -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	!		
Clutch			
Clutch Functioning	!		
Equipments Test			
Other Equipments	!	AC / Heating System	!
Levels			
Brakes Fluid	✓	Coolant Fluid	!

Test Drive Inspection

Other Checks			
Steering	✓	Brakes	✓
Suspension	!		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓		
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	!
Engine Noise	!		
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			