



Hüsge Gruppe®
Die Gutachter

status report

customer: BCA Autoauktionen GmbH

reference:

vehicle data

Maserati Levante

Vehicle identification number	ZN6TU61B00X253417	mileage read:	201366 km
..			
First Registration / construction year:	12.01.2018 / 2016	Visit Date / place of birth:	04.09.2025 Hoppegarten
Bodywork:	SUV	Re - import:	no
Body type:	hatchback	KBA no. :	4014//AAZ
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	2987 ccm / 202 kW (275 PS)	Engine:	four-wheel
paint:	black	Number of previous owners:	2
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	leather
Service book available:	no	Interior Color:	black
smoking vehicle:	no	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle	Eg II (veh - letter)	state outside:	3 - Average
documents:			
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided /	Last service at / on:
Hard Disk Drive	2	maintained:	- / -
		no / 6	
<input checked="" type="checkbox"/> Fernbed . Auxiliary heating	<input checked="" type="checkbox"/> partition net	<input checked="" type="checkbox"/> Wind Deflector	<input checked="" type="checkbox"/> AHK fixed
<input checked="" type="checkbox"/> AHK removable	<input checked="" type="checkbox"/> AHK swivel	<input checked="" type="checkbox"/> AHK key	<input checked="" type="checkbox"/> Fernbed . entertainment
<input checked="" type="checkbox"/> headphone	<input checked="" type="checkbox"/> Load compartment cover	<input checked="" type="checkbox"/> LED headlights	<input checked="" type="checkbox"/> navigation system
<input checked="" type="checkbox"/> Persenning	<input checked="" type="checkbox"/> Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires

Tyre / wheel type:	Winter tires	aluminum
1st axis - Left / states .	Falken	255/60/R18/112V 5 mm
1st axis - right / states .	Falken	255/60/R18/112V 5 mm
2nd axis - Left / states .	Falken	255/60/R18/112V 5 mm
2nd axis - right / states .	Falken	255/60/R18/112V 5 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment

special Features

standard equipment

- | | |
|--------------------------------|-------------------|
| • ABS | • four-wheel |
| • Power side mirrors . | • board computer |
| • DSTC | • ESP |
| • Built-in GPS | • Power windows |
| • Driver and passenger airbags | • Climate Control |
| • Multifunction steering wheel | • power steering |
| • TCS | • central locking |

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	Conducted limited To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	Steinschlag Frontscheibe

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage
---	--

**Layers of paint thickness
measurement:**

could be detected .

Within the tolerances











At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.

Existing collision damage:

Not established

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			examined limited		
oil loss:			examined limited		
air conditioning:			examined limited	lighting system:	
			examined limited		
coupling:			unavailable	exhaust System:	
			examined limited		
engine running:			examined limited	shock absorber:	
			examined limited		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fzg. weist rundum erhöhte Lackschichtwerte auf Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen.

damage



component	Damage	Rep kind
1. proof of maintenance	Missing	Replace
2. maintenance	Due	Replace
3. Sommerradsatz	Not available	Replace
4. Windshield	Chipping from stones	Replace
5. Door Rear - right	Scratch(es)	Smart repair
6. Front fender - right	Damaged	Paint
7. Front fender - left	Wear and tear	acceptable
8. Roof frame - left	Delle	Gentle refurbishing
9.	Damaged	Smart repair
10. Türeinstieg Vorne - Links	Scratch(es)	Paint

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



Navigation system



2. maintenance



4. Windshield



5. Door Rear - right



6. Front fender - right



6. Front fender - right



7. Front fender - left



8. Roof frame - left



9.



10. Türeinstieg Vorne - Links