DEKRA

DEKRA Automotive Solutions

Appraisal Report

DEKRA

Vehicle details

VIN	W0V7D9EE3 L4370034	Brand	OPEL	Maintenance date	-
Licence Plate	J3-38-TS	Model	Crossland X 1.2 S;S 60Kw ACTI 5d Edition 2020 APL	Maintenance mileage	-
Registration date	21/10/2020	Year	2020	Exterior Color	Red Metallic
Odometer	97 367 km	Engine size	1199	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	12/11/2025	Inspection loc.	Dekra Ayvens

Generic equipment

Automated air-conditioning	✔
Cruise control	✔
GPS system	✔
Alloy wheel rims	✔
Metallic paint	✔
Central locking	✔
Electric windows	✔
Side rails	✔
Park Distance Control	✔
Audio System	✔
Led lighting	✔

Removable element

Spare wheel (wheel & tyre)	✔
Rear parcel shelf	✖

Technical Document

User manual	✔
Warranty booklet	✔
Remote key	✔
Sat Nav CD ROM Software	✔
Spare key	✖

Tyres

Winter kit

Pirelli 195/60/16 Winter 5.5 mm

Pirelli 195/60/16 Winter 5.5 mm



Pirelli 195/60/16 Winter 5.5 mm

Pirelli 195/60/16 Winter 5.5 mm

Exterior

3

Part	Wing
Position	Front left
Damages	Improper repair
Severity	-
Repair mode	Repair

4

Part	Bumper
Position	Back
Damages	Dented
Severity	-
Repair mode	Replace

5

Part	Bumper moulding
Position	Back
Damages	Scratched
Severity	-
Repair mode	Repair

6

Part	Alloy wheel 16"
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

7

Part	Door
Position	Back right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

8

Part	Door
Position	Front right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

9

Part	Winter Tyre 16"
Position	Front right
Damages	Not conform
Severity	-
Repair mode	For info

10

Part	Wing moulding
Position	Front right
Damages	Not conform
Severity	-
Repair mode	Replace

11

Part	Bumper
Position	Front
Damages	Broken
Severity	-
Repair mode	Replace

12

Part	Bumper
Position	Front right
Damages	Missing
Severity	-
Repair mode	Adjust

13

Part	Fog lamp
Position	Front right
Damages	Missing
Severity	-
Repair mode	Replace

14



Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

15

Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

Interior damage

DEKRA Automotive Solutions

DEKRA

1		Part	Rear parcel shelf
		Position	-
		Damages	Missing
		Severity	-
		Repair mode	Replace
2		Part	Spare key
		Position	-
		Damages	Missing
		Severity	-
		Repair mode	Replace