MACADAM

Volkswagen Transporter: VDX30K

Vinnumber:	**WV1ZZZ7HZKH200475**	Versionname:	**Transporter 6 (Outgoing) 2.0 TDI 75kW GB L2H1**
First Registrationdate:	**16/04/2020**	Fiscalpower:	
Expertise Mileage:	**196024**	Power Kw:	**75**
Bodytype:		Body colour	**Candywit**
Gearbox:	**MAN 5 VIT**	Paint type	**Opaque**
Transmission:	**Front**	Type of rims (mounted)	**Steel**
Fueltype:	**Diesel**	Parking lot	**894**
Number of seats	**3**		
Type of rims (mounted)	**Steel**		
Maintenance needed	**Yes**		

Options

Number of keys total	**2**	Telephone equipment	
Manual climate control		Central consol F	
Windows electric F		Rear parking sensors	
Radio multimedia		Sliding door right-side	

Degree of wear

Summer tyres:	**205/65/16/107 T**			
	Fr.L.	**Bridgestone: 3,7 mm**	Fr.R.	**Bridgestone: 4,3 mm**
	Re.L.	**Bridgestone: 5,6 mm**	Re.R.	**Bridgestone: 7,2 mm**

Tyre profile depth FL	**3.7**
Tyre profile depth FR	**4.3**
Tyre profile depth RL	**5.6**
Tyre profile depth RR	**7.2**
Tyre size FL	**205/65 R 16 107 T**
Tyre size FR	**205/65 R 16 107 T**
Tyre size RL	**205/65 R 16 107 T**
Tyre size RR	**205/65 R 16 107 T**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**255**
Tyre make FR	**255**
Tyre make RL	**255**
Tyre make RR	**255**

Assistance equipment

Number of charging cables (normal)	**0**
Number of charging cables (rapid charge)	**0**

Service, Maintenance, Execute

Seat cover FL, Tear, Replace

Interior, Dirty, Cleaning

Door FL, Dent(s), Repair and paint (complete)

Side wall RL, Dent(s), Repair and paint (complete)

Bumper F, Broken, Replace

Side wall RR, Dent(s), Repair and paint (complete)

Sliding door R, Dent(s), Repair and paint (complete)

Shutter / cover R, Deformed / Strained, Replace

Rear light L, Crack, Replace

Boot door panel RL, Scratch(es), Repair and paint (complete)