

VW TIGUAN EHYBRID 1.4 TSI ACT OPF

Vehicle information

License plate	ZRM53J	Inspected by	A.A.
Year model	2023	Date of inspection	2025-10-28
Manuf. year/month	2022-10	City	Björkvik
First day in traffic	2022-10	Keys	2
Colour	Svart	Service book	Elektronisk servicebok
Mileage	117 080 km	Latest service	2024-09-16
Fuel	Elhybrid	Mileage at the latest service	74 630 km
Transmission	DSG Sekventiell	Summer tires	18" alu-fälg 3/3/3/3
Engine effect	110 kW	Winter tires	alu-fälg odubbbat 5/4/4/5

Damages

Location	Damage	Comments	Costs excluding VAT
Service, Not serviced	Missad service		370 €
Door, Rear left	Smart repair		70 €
Bumper, Rear	Smart repair	Lastrepor	70 €
Door, Rear right	Liten buckla/Repor	Skrapad	260 €
Recond, Dirty trim	Klädsel tvätt	Passagerare sätet	150 €
Bumper, Front	Smart repair		70 €
Bonnet, Bonnet	Smart repair		70 €
Total excl. VAT			1 060 €

Images

[See all images in large format](#)



















Serviceprotokoll



Modellkod	AX14ZY	Registreringsnr	ZRM53J	Registrering	2022-11-17
MMB	DGEA	Mätarställning	74638	Serviceraðgivare	
VMB	UCY	Årsmodell	2023	Datum	16.09.2024

Inspektion med oljebyte

	Ok/genomförd	Inte ok	åtgärdat
Innertaket, bagagerums- och handskfacksbelysning:	☒	☐	☐
ionen	☒	☐	☐
rollera funktionen	☒	☐	☐
rollera att den finns och inte har synliga skador			

























Dörr Vänster bak Smart repair 1 000 kr



Stötfångare Bak Smart repair Lastrepor 1 000 kr



Dörr Höger bak Liten buckla/Repor Skrapad 3 500 kr





Rekonstruktions Smutsig klädsel Klädsel tvätt Passagerare sätet 2 000 kr



Stötfångare Fram Smart repair 1 000 kr



Motorhuv Motorhuv Smart repair 1 000 kr





