

# Inspection Protocol

## TESLA MODEL Y STANDARD RANGE RWD, 299HK, 2023

### Vehicle information

<b>License plate</b>	TFN525	<b>Inspected by</b>	A.A.
<b>Year model</b>	2023	<b>Date of inspection</b>	2025-11-28
<b>Manuf. year/month</b>	2023-03	<b>City</b>	Björkvik
<b>First day in traffic</b>	2023-05	<b>Keys</b>	1
<b>Colour</b>	Svart	<b>Service book</b>	Elektronisk servicebok
<b>Mileage</b>	142 240 km	<b>Latest service</b>	-
<b>Fuel</b>	EI (EV)	<b>Mileage at the latest service-</b>	
<b>Transmission</b>	Automat	<b>Summer tires</b>	19" alu-fälg 6/6/6/6
<b>Engine effect</b>	220 kW	<b>Winter tires</b>	alu-fälg dubbat 8/8/8/8

### Damages

Location	Damage	Comments	Costs excluding VAT
Keys, Reservnyckel	Missing		110 €
Skärm , Front left	Smart repair		70 €
Door, Front left	Smart repair		70 €
Skärm , Rear left	Smart repair		70 €
Bumper, Rear	Smart repair		70 €
Bumper, Front	Smart repair		70 €
Bonnet, Bonnet	Smart repair	Många stenskott	70 €
Rims, Aluminum rim	Damage	Hf	220 €
Rims, Aluminum rim	Damage	Hb	220 €
Rims, Aluminum rim	Damage	Vf	220 €
Glass, Windshield	Stenskott/Spricka		-

---

**Total excl. VAT** 1 190 €

### Images

[See all images in large format](#)




























Skärm Vänster fram Smart repair 1 000 kr



Dörr Vänster fram Smart repair 1 000 kr



Skärm Vänster bak Smart repair 1 000 kr



Stötfångare Bak Smart repair 1 000 kr



Stötfångare Fram Smart repair 1 000 kr



Motorhuv Motorhuv Smart repair Många stenscott 1 000 kr



Fälgar Aluminiumfälg Skada Hf 3 000 kr



Fälgar Aluminiumfälg Skoda Hb 3 000 kr



Fälgar Aluminiumfälg Skoda Vf 3 000 kr



Glas Vindruta Stenskott/Spricka





