



TOYOTA COROLLA TOURING SPORTS: 1YWQ596			
Vinnumber:	SB1Z93BE30E144849	Versionname:	1.8 Hybrid Trek Plus e-CVT
First Registrationdate:	13/01/2021	Fiscalpower:	
Expertise Mileage:	98223	Power Kw:	90
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2215
Fueltype:	Hybrid Petrol		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Options			
Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Limited Technical Inspection			
Tyres			
Summer tyres:	225/45/17/92 H		
	Fr.L.	Uniroyal: 5 mm	Fr.R. Uniroyal: 5 mm
	Re.L.	Uniroyal: 5 mm	Re.R. Uniroyal: 5 mm
Tyre profile depth FL			5
Tyre profile depth FR			5
Tyre profile depth RL			5
Tyre profile depth RR			5
Tyre size FL			225/45 R 17 92
Tyre size FR			225/45 R 17 92
Tyre size RL			225/45 R 17 92
Tyre size RR			225/45 R 17 92
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			265
Tyre make FR			265
Tyre make RL			265
Tyre make RR			265
Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		
Total cost ex VAT			2230,71
Bumper spoiler F, Scratch(es), Smart repair			113,74

 	Bumper moulding F, Scratch(es), Acceptable	0,00
 	Bumper F, Scratch(es), Acceptable	0,00
 	Windscreen, Crack, Replace	787,21
 	Wing RL, Bad repair, Check	0,00
 	Bumper R, Scratch(es), Acceptable	0,00
 	Alloy rim FR polished, Scratch(es), Repair and paint (complete)	199,04
 	Door FR, Dent(s), Repair and paint (complete)	434,50
 	Door RR, Scratch(es), Repair and paint (complete)	434,50
 	Wing RR, Scratch(es), Acceptable	0,00
 	Wing trim RR, Scratch(es), Replace	62,68



Alloy rim RR polished, Scratch(es), Repair and paint (complete)	199,04
---	--------

