

Inspection Protocol

HYUNDAI TUCSON PHEV

Vehicle information

License plate	XUF31X	Inspected by	C.C.
Year model	2022	Date of inspection	2025-10-24
Manuf. year/month	2022-09	City	Björkvik
First day in traffic	2022-09	Keys	2
Colour	Grå	Service book	Elektronisk servicebok
Mileage	48 630 km	Latest service	-
Fuel	Elhybrid	Mileage at the latest service -	
Transmission	Automat	Summer tires	19" alu-fälg 4/4/4/4
Engine effect	195 kW	Winter tires	alu-fälg dubbat 7/7/7/7

Damages

Location	Damage	Comments	Costs excluding VAT
Rims, Aluminum rim	Damage	1st	220 €
Bumper, Rear	Repa/Repor		260 €
Skärm , Rear right	Liten buckla/repor		440 €
Skärm , Front right	Repa/Repor		180 €
Door, Rear left	Repa/Repor		150 €

Total excl. VAT	1 250 €
------------------------	----------------

Images

[See all images in large format](#)

























Fälgar Aluminiumfälg Skada 1st 3 000 kr



Dörr Vänster bak Repa/Repor 2 000 kr



Stötfångare Bak Repa/Repor 3 500 kr



Skärm Höger bak Liten buckla/repor 6 000 kr



Skärm Höger fram Repa/Repor 2 500 kr