



SKODA SUPERB COMBI: 1WXZ021

Vinnnumber:	TMBJH7NP3L7025790	Versionname:	2.0 CRTDI 110kW Ambition
First Registrationdate:	22/10/2019	Fiscalpower:	
Expertise Mileage:	93338	Power Kw:	110
Bodytype:		Body colour:	Blue
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	1315
Fueltype:	Diesel		
Maintenance:	NOT OK		
Maintenance:	onderhoud nu		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Seats electric F L:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Seats F heated:		Type of Tow bar:	Tow bar collapsible
Radio multimedia:			
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		
Type of GPS storage:	SD present		

Limited Technical Inspection

Degree of wear

	215/60/16/95 V			
Summer tyres:	Fr.L.	Falken: 2 mm	Fr.R.	Falken: 2 mm
	Re.L.	Falken: 5 mm	Re.R.	Falken: 4 mm
Tyre profile depth FL				2.0
Tyre profile depth FR				2.0
Tyre profile depth RL				5.0
Tyre profile depth RR				4.0
Tyre size FL				215/60 R 16 95 V
Tyre size FR				215/60 R 16 95 V
Tyre size RL				215/60 R 16 95 V
Tyre size RR				215/60 R 16 95 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				1957074
Tyre make FR				1957074
Tyre make RL				1957074
Tyre make RR				1957074

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT:	1270,69
Door panel RL, Broken, Forfeit:	13,65



Air vent RM, Broken, Replace

27,05



Service, Maintenance, Check

0,00



Bonnet, Scratch(es), Acceptable

0,00



Bumper F, Scratch(es), Acceptable

0,00



Wing FL, Bad repair, Repair and paint (complete)

360,60



Door FL, Scratch(es), Acceptable

0,00



Door RL, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00





Bumper trim R, Scratch(es), Forfeit

25,00



Tailgate / Boot, Dent(s), Paintless dent repair

93,06



Luggage compartment cover, Missing, Replace

246,56



Wing RR, Scratch(es), Repair and paint (complete)

504,77



Door RR, Scratch(es), Acceptable

0,00



Door FR, Scratch(es), Acceptable

0,00

