

Inspection Protocol



SKODA OCTAVIA SCOUT 2.0 TDI 4X4

Vehicle information

License plate	BSZ456	Inspected by	A.H.
Year model	2015	Date of inspection	2025-03-13
Manuf. year/month	2014-09	City	Falkenberg
First day in traffic	2014-10	Keys	2
Colour	Vit	Service book	Elektronisk servicebok
Mileage	212 640 km	Latest service	-
Fuel	Diesel	Mileage at the latest service -	
Transmission	DSG Sekventiell	Summer tires	17" alu-fälg 5/5/6/6
Engine effect	135 kW	Winter tires	alu-fälg dubbat 6/9/9/6

Damages

Location	Damage	Comments	Costs excluding VAT
Inredning, Boot	Boot cover missing		460 €
Tow bar	Other	Sitter skruv i dragkrokslåset	-
Engine and Transmission, Motor	Other	Olje fukt	-
Door, Lef side mirror	Paint retouch traces		10 €
Other, Other	Other	Sliten ratt	-
Bumper, Rear	Cracks 30 mm-100 mm		300 €
Tak, A-pillar	Stenskott/ repa	Höger	10 €
Other, Other	Regskylt fram inbuktningar		10 €
Bumper, Front	Chips, several		70 €
Bonnet	Pitted		340 €
Glass, Windshield	Cracks small (max 30 mm)		270 €
Tak, Tak	Chip		70 €
Other, Other	Other	Komplett bilmapp saknas	-

Total excl. VAT	1 540 €
-----------------	---------

Images

[See all images in large format](#)



















Dragkrok Övrigt Sitter skruv i dragkrokslåset



Dörr Vänster backspegel Lackbättring 50 kr



Övrigt Övrigt Övrigt Sliten ratt



Stötfångare Bak Sprickor, 3-10 cm 3 300 kr



Tak A-stolpe Stenskott/ repa Höger 50 kr




Övrigt Övrigt Regskylt fram inbuktningar 100 kr




Stötfångare Fram Stenskott flertal 800 kr



Motorhuv Stenskott (blästrad) 3 700 kr



Glas Vindruta Sprickor små (max 3 cm) 3 000 kr



Tak Tak Stenskott 800 kr



Motor och Väckellåda Motor Övrigt Olje fukt





