


MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia											
				Policyholder				Opposite party				Opposite party company									
				Operation 2025		Claim number			Code / Agency				Date accident 18/09/2025								
				Expert code		Adjuster code			Policy number				Injured person can recover the VAT								
Date assignment 18/09/2025		Date first survey 25/09/2025		Place POMEZIA		C/O VAR		Repairs TO START		Photo		Lien in favor of		Expiry date							
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)														Formerly plate							
Lessee / Co-owner														Date of overhaul							
Vehicle (Brand - Model - Version) RENAULT MASTER FG TA L2 H2 T33 dCi 135 start MY23 furgone 135CV 4P								Plate GT354XY		Vin Chassis VF1MA000172850456				First Registration 29/03/2024							
Usage status NON CONOSCIUTO		Km 38269		Tyres % 35		Color BIANCO		Type of enamel METALLIZED/DOUBLE				Consistency of damage		Type of Expert's report NOT DEFINITIVE							
Equipment																					
Approval code		For commercial vehicles		Carrying Qls 0		Tare, Q 0										Wheelbase		Seats No. 0		Axles 0	
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses															
Damaged items / restoration operations								SR		LA		VE		ME		D.M. S.C.		Costs of spare parts			
								Dif Time		Dif Time		Dif Time		Time				* (VAT excluded)			
1		850224674R		Rear central bumper				S		S		S									
1		850160036R		Rear side bumper				R S		S		S									
1		760325069R		Side rear wall				R L		L		L									
1		767503261R		Rear internal wheel arch				L L		L		L									
1		767503261R		Rear internal wheel arch				R M		M		M									
1		997900002R		Tyre inflation compressor				S		S		S									
1		Codice Ricambio		Bomboletta gonfiaggio pneumatici				S		S		S									
1		Codice Ricambio		N. 2 Pneumatici ant.ri				S		S		S									

New for old value (N)	Remarks PNEUM ESTIVI BRIDGESTONE 225/65/16C VHL SPORCO E RILEV SEGNALE SU QUADRO STRUM.: RIGENERARE FAP INUTILE E CONTROLLARE PLACCHETTE FRENO
-----------------------	---