



PEUGEOT 308 SW: 1YTV287

Vinnumber:	VF3LCYHZKLS247517	Versionname:	1.5 BlueHDi 130 S&S EAT8 Allure Pack
First Registrationdate:	11/12/2020	Fiscalpower:	
Expertise Mileage:	139942	Power Kw:	96
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2703
Fueltype:	Diesel		
Maintenance	NOT OK		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	No		
Category	Passenger Car		
Registration Certificate Car (BE)	No		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

	205/55/16/91 H			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/55 R 16 91 H
Tyre size FR				205/55 R 16 91 H
Tyre size RL				205/55 R 16 91 H
Tyre size RR				205/55 R 16 91 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	5008,69
Service, Maintenance, Check	0,00



Steering wheel, Worn, Acceptable	0,00
----------------------------------	------



Registration document, Missing, Replace	187,67
---	--------



Certificate Of Conformity, Missing, Replace	187,67
---	--------



Bumper F, Scratch(es), Repair and paint (complete)	289,07
--	--------



Bonnet, Dent(s) and scratch(es), Repair and paint (complete)	395,90
--	--------




Outer sill L, Scratch(es), Acceptable	0,00
---------------------------------------	------



Alloy rim RL, Scratch(es), Repair and paint (complete)	129,66
--	--------



Door RL, Scratch(es), Acceptable	0,00
----------------------------------	------



Outside rear-view mirror housing L, Scratch(es), Acceptable	0,00
---	------



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)

445,51



Roof pillar L, Dent(s), Paintless dent repair

93,06




Bumper R, Scratch(es), Acceptable

0,00



Boot carpet, Damaged, Replace

407,88



Tailgate / Boot, Scratch(es), Repair and paint (complete)

411,74



Brand badge R, Deformed / Strained, Replace

76,56



Rear window, Scratch(es), Replace

326,39



Bumper R, Scratch(es), Repair and paint (complete)

289,07






Alloy rim RR, Scratch(es), Repair and paint (complete)	129,66
--	--------



Alloy rim FR, Scratch(es), Repair and paint (complete)	129,66
--	--------



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)	539,79
--	--------



Door FR, Scratch(es), Acceptable	0,00
----------------------------------	------



Door RR, Dent(s) and scratch(es), Repair and paint (complete)	434,50
---	--------



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)	507,65
---	--------



Bodywork, Not original part, Remove lettering	0,00
---	------



Aerial, Missing, Replace	27,25
--------------------------	-------

