



PEUGEOT 308 SW: 1YBP302

Vinnumber:	VF3LJEHZRKS510333	Versionname:	2.0 BlueHdi 180 DPF S&S EAT8 GT
First Registrationdate:	8/07/2020	Fiscalpower:	
Expertise Mileage:	153104	Power Kw:	132
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	1728
Fueltype:	Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	1	Seats electric F L	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

225/40/18/92 H				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/40 R 18 92 H
Tyre size FR				225/40 R 18 92 H
Tyre size RL				225/40 R 18 92 H
Tyre size RR				225/40 R 18 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	5576,59
Ignition key, Missing, Replace	341,22



Seat cover FL, Worn, Acceptable	0,00
---------------------------------	------



Bonnet, Chemical polution, Repair and paint (complete)	395,90
--	--------



Bumper F, Scratch(es), Repair and paint (complete)	289,07
--	--------



Wing RL, Dent(s), Repair and paint (complete)	420,65
---	--------



Alloy rim RL, Scratch(es), Repair and paint (complete)	129,66
--	--------



Step L, Scratch(es), Acceptable	0,00
---------------------------------	------



Door FL, Scratch(es), Acceptable	0,00
----------------------------------	------



Alloy rim FL, Scratch(es), Repair and paint (complete)	129,66
--	--------



Boot carpet, Dirty, Cleaning	28,43
------------------------------	-------



Boot carpet, Scratch(es), Replace 581,83



Luggage compartment cover, Damaged, Replace 581,83



Bumper R, Scratch(es), Repair and paint (complete) 289,07



Tailgate / Boot, Scratch(es), Acceptable 0,00




Rear window, Scratch(es), Acceptable 0,00




Alloy rim FR, Scratch(es), Repair and paint (complete) 129,66



Wing FR, Scratch(es), Repair and paint (complete) 300,51



Door FR, Scratch(es), Repair and paint (complete) 434,50



Door RR, Scratch(es), Repair and paint (complete) 434,50



Sill trim R, Scratch(es), Repair and paint (complete) 423,79



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)

536,65



Alloy rim RR, Scratch(es), Repair and paint (complete)

129,66



Roof, Dent(s), Acceptable

0,00

