

Inspection Protocol



SEAT LEON ST 1.5 TGI

Vehicle information

License plate	HUB67R	Inspected by	A.A.
Year model	2020	Date of inspection	2025-10-29
Manuf. year/month	2020-06	City	Björkvik
First day in traffic	2020-07	Keys	2
Colour	Vit	Service book	Elektronisk servicebok
Mileage	37 150 km	Latest service	2025-09-25
Fuel	Gas	Mileage at the latest service	36 610 km
Transmission	DSG Sekventiell	Summer tires	16" alu-fälg 7/6/6/7
Engine effect	96 kW	Winter tires	alu-fälg odubbbat 8/7/7/8

Damages

Location	Damage	Comments	Costs excluding VAT
Door, Lef side mirror	Scratches below 30 mm		60 €
Recond	Interior	Klädsel tvätt förare sätet	60 €
Bumper, Rear	Cargo scratches		150 €
Inredning, Boot	Tears		150 €
Recond	Interior	Klädsel tvätt passagerare sätet	60 €
Wing, Front right	Scratches 30-100 mm		80 €
Bumper, Front	Scratches below 30 mm		60 €
Bonnet	Chip		60 €
Boot lid, Boot lid	Dents below 30 mm		60 €
Glass, Windshield	Chip		20 €
Total excl. VAT			760 €

Service occasions

1000-MIL, 2500-MIL, 3000-MIL, 3500-MIL

Images

[See all images in large format](#)





















Dörr Vänster backspegel Repor under 3 cm 800 kr



Rekond Invändig Klädsel tvätt förare sätet 800 kr



Stötfångare Bak Lastrepör 2 000 kr



Inredning Bagageutrymme Revor 2 000 kr



Rekonstrering av inre klädsel tvätt passagerare sätet 800 kr



Skärning av höger fram Repor 3-10 cm 1 100 kr



Stötfångare Fram Repor under 3 cm 800 kr



Motorhuv Stenskott 800 kr



Bagagelucka Bagagelucka Bucklor under 3 cm 800 kr



Glas Vindruta Stenskott 300 kr





