



MERCEDES B: 1YNU570

| | | | |
|-------------------------------------|--------------------------|-------------------------|------------------|
| Vinnumber: | W1K2470871J209275 | Versionname: | B 200 |
| First Registrationdate: | 14/10/2020 | Fiscalpower: | |
| Expertise Mileage: | 85683 | Power Kw: | 120 |
| Bodytype: | | Body colour: | Grey |
| Gearbox: | MAN 6 VIT | Type of rims (mounted): | Aluminium |
| Transmission: | | Parking lot: | 1322 |
| Fueltype: | Petrol | | |
| Type of rims (mounted): | Aluminium | | |
| Certificate of Conformity: | Yes | | |
| Category: | Passenger Car | | |
| Registration Certificate Car (BE): | Yes | | |
| Registration Certificate Home (BE): | No | | |

Options

| | | | |
|--------------------------------|--|-----------------------|-------------------|
| Number of keys total: | 2 | Sun Roof electric | |
| Cruise Control | | Panoramic roof | |
| Steering wheel multifunctional | | Luggage cover | |
| Radio multimedia | | Front parking sensors | |
| Type of headlighting: | Headlighting LED | Rear parking sensors | |
| Type of GPS: | GPS big screen color | Type of Tow bar: | No Tow bar |
| Type of Lining: | Lining artificial leather and alcantara | | |
| Type of climate control: | Autom climate control | | |

Limited Technical Inspection

Tyres

| | | | | |
|-----------------------|-------|--------------------------|-------|--------------------------|
| 225/45/18/95 Y | | | | |
| Summer tyres: | Fr.L. | Uniroyal: 5 mm | Fr.R. | Uniroyal: 5 mm |
| | Re.L. | Bridgestone: 5 mm | Re.R. | Bridgestone: 5 mm |

| | |
|-----------------------|-------------------------|
| Tyre profile depth FL | 5.0 |
| Tyre profile depth FR | 5.0 |
| Tyre profile depth RL | 5.0 |
| Tyre profile depth RR | 5.0 |
| Tyre size FL | 225/45 R 18 95 Y |
| Tyre size FR | 225/45 R 18 95 Y |
| Tyre size RL | 225/45 R 18 95 Y |
| Tyre size RR | 225/45 R 18 95 Y |
| Tyre type FL | Summer |
| Tyre type FR | Summer |
| Tyre type RL | Summer |
| Tyre type RR | Summer |
| Tyre make FL | 265 |
| Tyre make FR | 265 |
| Tyre make RL | 255 |
| Tyre make RR | 255 |

Assistance equipment

| | | | |
|---|------------|-------------|------------|
| Repair kit: | Yes | Compressor: | Yes |
| Number of charging cables (normal): | 0 | | |
| Number of charging cables (rapid charge): | 0 | | |

| | |
|--------------------------|---------------|
| Total cost ex VAT | 756,07 |
|--------------------------|---------------|

| | |
|----------------------------------|---------------|
| Interior, Dirty, Cleaning | 170,61 |
|----------------------------------|---------------|



Bumper moulding F, Broken, Replace 97,35




Bumper F, Crack, Repair and paint (complete) 289,07



Alloy rim RL polished, Scratch(es), Acceptable 0,00



Step L, Scratch(es), Acceptable 0,00



Damage Picture - 1

Alloy rim FL polished, Scratch(es), Repair and paint (complete) 199,04



Door RL, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00



Alloy rim RR polished, Scratch(es), Acceptable 0,00



Alloy rim FR polished, Scratch(es), Acceptable 0,00



Roof pillar R, Dent(s), Acceptable 0,00

