



Audi A5: 2BCH364				
Vinnnumber:	WAUZZZF55NA003706	Versionname:	AUDI A5 SPORTBACK 35 TFSI S tronic Bus. Ed.	
First Registrationdate:	29/09/2021	Fiscalpower:	Advanced 150PK 5d/p AUT (F5FB7G)	
Expertise Mileage:	184668	Power Kw:	110	
Bodytype:		Body colour	Black	
Gearbox:	Automatic	Type of rims (mounted)	Aluminium	
Transmission:		Parking lot	2720	
Fueltype:	Hybrid Petrol			
Maintenance	OK			
Type of rims (mounted)	Aluminium			
Certificate of Conformity	Yes			
Category	Passenger Car			
Registration Certificate Car (BE)	Yes			
Registration Certificate Home (BE)	No			
Options				
Number of keys total	2	Seats electric F L		
Cruise Control		Seats electric F R		
Steering wheel multifunctional		Sun Roof electric		
Seats F heated		Panoramic roof		
Radio multimedia		Luggage cover		
Type of headlighting	Headlighting Xenon	Front parking sensors		
Type of GPS	GPS big screen color	Rear parking sensors		
Type of Lining	Lining leather	Type of Tow bar	Tow bar removable	
Type of climate control	Autom climate control			
Type of GPS storage	HD			
Limited Technical Inspection				
Tyres				
Summer tyres:	245/40/18/97 Y			
	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 6 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				6.0
Tyre size FL				245/40 R 18 97 Y
Tyre size FR				245/40 R 18 97 Y
Tyre size RL				245/40 R 18 93 H
Tyre size RR				245/40 R 18 93 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				261
Tyre make RR				261
Assistance equipment				
Emergency spare wheel	Yes	Jack	Yes	
Number of charging cables (normal)	0			
Number of charging cables (rapid charge)	0			
Total cost ex VAT			1413,06	
Seat cover FL, Worn, Acceptable			0,00	



Backrest cover FL, Worn, Acceptable	0,00
-------------------------------------	------



Door panel FL, Worn, Acceptable	0,00
---------------------------------	------



Ignition key, Missing, Replace	409,46
--------------------------------	--------



Bumper moulding F, Broken, Replace	27,35
------------------------------------	-------



Alloy rim RL, Scratch(es), Acceptable	0,00
---------------------------------------	------



Mirror side repeater L, Broken, Replace	75,61
---	-------



Alloy rim FL, Scratch(es), Repair and paint (complete)	129,66
--	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------



Wing FR, Dent(s), Repair and paint (complete)	418,60
---	--------



Alloy rim FR, Scratch(es), Repair and paint (complete)

129,66



Door FR, Dent(s), Acceptable

0,00



Door RR, Dent(s), Paintless dent repair

93,06



Alloy rim RR, Scratch(es), Repair and paint (complete)

129,66



Wing RR, Scratch(es), Acceptable

0,00



Bodywork, Not original part, Check

0,00

