



BMW X1: 2AEY429			
Vinnumber:	WBA31AA0X05T32784	Versionname:	sDrive18iA (100 kW)
First Registrationdate:	12/03/2021	Fiscalpower:	
Expertise Mileage:	34837	Power Kw:	100
Bodytype:		Body colour:	White
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	3630
Fueltype:	Petrol		
Maintenance:	OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options			
Number of keys total:	2	Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		
Type of GPS storage	HD		

Limited Technical Inspection

Degree of wear

225/50/18/99 V				
Winter tyres:	Fr.L.	Vredestein: 4 mm	Fr.R.	Vredestein: 4 mm
	Re.L.	Vredestein: 4 mm	Re.R.	Vredestein: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				225/50 R 18 99 V
Tyre size FR				225/50 R 18 99 V
Tyre size RL				225/50 R 18 99 V
Tyre size RR				225/50 R 18 99 V
Tyre type FL				Winte
Tyre type FR				Winte
Tyre type RL				Winte
Tyre type RR				Winte
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Number of charging cables (normal)	0	
Number of charging cables (rapid charge)	0	
Total cost ex VAT		1593,74
Seat cover FR, Stain, Cleaning		28,43



Seat cover RL, Stain, Cleaning

28,43



Bumper F, Stone chip(s), Acceptable

0,00



Bonnet, Dent(s), Repair and paint (complete)

0,00



Grille, Crack, Replace

142,55



Headlight R, Scratch(es), Replace

0,00



Door FL, Scratch(es), Repair and paint (complete)

434,50



Wing RL, Scratch(es), Repair and paint (complete)

420,65



Tyre repair kit, Missing, Replace

0,00



Interior covering C pillar L, Scratch(es), Replace

92,40



Bumper R, Scratch(es), Repair and paint (complete)

289,07



Bumper moulding R, Scratch(es), Repair and paint (complete)	157,71
---	--------



Door RR, Dent(s), Acceptable	0,00
------------------------------	------



Door FR, Dent(s), Acceptable	0,00
------------------------------	------



Wing RR, Dent(s), Acceptable	0,00
------------------------------	------

