



BMW 1 HATCH: 1XRG109

Vinnnumber:	WBA7K310205R55486	Versionname:	118iA (103 kW)
First Registrationdate:	16/03/2020	Fiscalpower:	
Expertise Mileage:	34829	Power Kw:	103
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2614
Fueltype:	Petrol		
Maintenance:	OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Radio multimedia:		Type of Tow bar:	No Tow bar
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		
Type of GPS storage:	HD		

Limited Technical Inspection

Degree of wear

205/55/16/91 W				
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				205/55 R 16 91 W
Tyre size FR				205/55 R 16 91 W
Tyre size RL				205/55 R 16 91 W
Tyre size RR				205/55 R 16 91 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		
Total cost ex VAT			2308,78
Bumper moulding F, Missing, Replace			131,39



Bumper F, Scratch(es), Repair and paint (complete)

289,07



Bonnet, Scratch(es), Repair and paint (complete)

395,90



Wing FL, Scratch(es), Repair and paint (complete)

300,51



Outside rear-view mirror housing L, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Repair and paint (complete)

289,07



Alloy rim RR, Scratch(es), Repair and paint (complete)

129,66



Roof, Dent(s), Repair and paint (complete)

773,18

