

Vehicle details

VIN	WF02XXERK 2LT33988	Brand	FORD	Maintenance date	-
Licence Plate	K0-91-KN	Model	PUMA 1.0 EcoBoost Hybrid Titanium 5d ActieAuto APL	Maintenance mileage	-
Registration date	19/01/2021	Year	2021	Exterior Color	White Solid
Odometer	61 473 km	Engine size	999	interior Color	Grey
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	04/09/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Pirelli 215/55/17 Summer 6.0 mm



Pirelli 215/55/17 Summer 6.0 mm



Goodyear 215/55/17 Summer 6.0 mm

Goodyear 215/55/17 Summer 6.0 mm


Exterior

1



Part	Exterior door mirror shell
Position	Left
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

2



Part	Wing
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

3



Part	Bumper
Position	Back
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

4



Part	Step plate
Position	Back right
Damages	Dent & Chips
Severity	-
Repair mode	For info

5



Part	Door
Position	Back right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

6



Part	Door
Position	Front right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

7



Part	Wing moulding
Position	Front right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

8



Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

9



Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

10



Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

11



Part	Upper tailgate / Boot
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair