



FORD TRANSIT CONNECT: 1XJE437

Vinnnumber:	WF0SXXWPGSKP54750	Versionname:	1.5 TDCi 88kW L2 HD Trend
First Registrationdate:	14/01/2020	Fiscalpower:	
Expertise Mileage:	133436	Power Kw:	88
Bodytype:		Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:		Parking lot:	3532
Fueltype:	Diesel		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Light Commercial Vehicle		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Rear parking sensors:	
Cruise Control:		Type of Tow bar:	No Tow bar
Steering wheel multifunctional:			
Radio multimedia:			
Type of headlighting:	Headlighting Halogen		
Type of GPS:	No GPS		
Type of Lining:	Lining fabrics		
Type of climate control:	Manual climate control		

Limited Technical Inspection

Degree of wear

205/60/16/96 H				
Winter tyres:	Fr.L.	Semperit: 5 mm	Fr.R.	Semperit: 5 mm
	Re.L.	Semperit: 5 mm	Re.R.	Semperit: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/60 R 16 96 H
Tyre size FR				205/60 R 16 96 H
Tyre size RL				205/60 R 16 96 H
Tyre size RR				205/60 R 16 96 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2477
Tyre make FR				2477
Tyre make RL				2477
Tyre make RR				2477

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT:	2494,76
Interior, Worn, Acceptable:	0,00



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)

216,80



Windscreen, Scratch(es), Replace

807,41



Wheel cover FL, Scratch(es), Replace

44,73



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)

225,37



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)

315,48



Wheel cover RL, Missing, Replace

44,73



Bumper R, Dent(s) and scratch(es), Replace

377,72



Bumper trim R, Scratch(es), Replace

462,52

Bumper with R, scratches, Replace

102,92



Bodywork, Not original part, Remove lettering

0,00

