

Inspection Protocol



VW TRANSPORTER T32 2.0 TDI BMT

Vehicle information

License plate	EMM57T	Inspected by	T.H.
Year model	2019	Date of inspection	2025-10-20
Manuf. year/month	2019-05	City	Björkvik
First day in traffic	2019-06	Keys	2
Colour	Svart	Service book	Elektronisk servicebok
Mileage	141 150 km	Latest service	-
Fuel	Diesel	Mileage at the latest service -	
Transmission	DSG Sekventiell	Summer tires	16" alu-fälg 3/3/3/3
Engine effect	110 kW	Winter tires	saknas

Damages

Location	Damage	Comments	Costs excluding VAT
Service	Due now		360 €
Wing, Filler cap	Scratches above 100 mm		150 €
Door, Left sliding door	Paint damages		-
Boot lid, Boot lid	Scratches above 100 mm		180 €
Door, Front right	Scratches 30-100 mm		80 €
Door, Right sliding door	Paint damages		-
Wing, Front right	Scratches 30-100 mm		80 €
Bonnet	Chips, several		160 €
Glass, Windshield	Cracks long (Above 150 mm)		510 €
Engine and Transmission, Motor	Other	Motorlampa lyser. Felkod: p201500 Om motorkontrolllampan lyser på din Volkswagen Transporter och felkoden som visas är P201500 (eller liknande P2015) så handlar det troligen om ett problem med insugsrörets flapp/ställmotor och/eller sensor. Här är vad koden betyder och vad man bör göra:	-
Brakes and Chassi, Front Part	Noise	Missljud från vänster fjädring	150 €
Total excl. VAT			1 670 €

Service occasions

11000-MIL

Images

[See all images in large format](#)














Motor och Växellåda Motor Övrigt Motorlampa lyser. Felkod: p201500 Om motorkontrolllampan lyser på din Volkswagen Transporter och felkoden som visas är P201500 (eller liknande P2015) så handlar det troligen om ett problem med insugsrörets flapp/ställmotor och/eller sensor. Här är vad koden betyder och vad man bör göra:





Skärm Tanklock Repor över 10 cm 2 000 kr



Dörr Vänster skjutdörr Lackskador



Bagagelucka Bagagelucka Repor över 10 cm 2 500 kr



Dörr Höger fram Repor 3-10 cm 1 100 kr



Dörr Höger skjutdörr Lackskador



Skärm Höger fram Repor 3-10 cm 1 100 kr



Motorhuv Stenskott flertal 2 200 kr



Glas Vindruta Sprickor långa (Över 15 cm) 7 000 kr