

Inspection Protocol

TRADING
SOLUTIONS

VW TIGUAN 2.0 TDI DPF SCR 4MOTION

Vehicle information

License plate	BHD74E	Inspected by	T.H.
Year model	2022	Date of inspection	2025-10-27
Manuf. year/month	2022-06	City	Björkvik
First day in traffic	2022-06	Keys	2
Colour	Silver	Service book	Elektronisk servicebok
Mileage	142 100 km	Latest service	-
Fuel	Diesel	Mileage at the latest service -	
Transmission	DSG Sekventiell	Summer tires	20" alu-fälg 5/5/5/5
Engine effect	147 kW	Winter tires	alu-fälg dubbat 5/5/6/6

Damages

Location	Damage	Comments	Costs excluding VAT
Rear fender, More than 2 damages left	Lack/rikt	Buckla samt repor	520 €
Front bumpers	Normalt slitage	Skrapad under	-
Motorhuv	Spot repair	Repa samt stenskott	180 €
Windshield, Reparation	1-3 stone chips	Normalt slitage	-
Service, Försenad	100-300 Mil/Över 1 mån		460 €

Total excl. VAT	1 160 €
-----------------	---------

Service occasions

Fordonet ska tvättas

Images

[See all images in large format](#)



























