



VOLKSWAGEN PASSAT VARIANT: 1UAJ848

Vinnnumber:	WVWZZZ3CZJE130124	Versionname:	1.6 TDI Comfortline Business DSG-7
First Registrationdate:	13/03/2018	Fiscalpower:	
Expertise Mileage:	180797	Power Kw:	88
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2810
Fueltype:	Diesel		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Radio multimedia:		Type of Tow bar:	Tow bar collapsible
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Degree of wear

215/60/16/99 H				
Winter tyres:	Fr.L.	Fulda: 3 mm	Fr.R.	Fulda: 4 mm
	Re.L.	Vredestein: 4 mm	Re.R.	Vredestein: 5 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				5.0
Tyre size FL				215/60 R 16 99 H
Tyre size FR				215/60 R 16 99 H
Tyre size RL				215/60 R 16 99 H
Tyre size RR				215/60 R 16 99 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2484
Tyre make FR				2484
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Emergency spare wheel:	Yes	Jack:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT:	2934,90
Interior, Damaged, Acceptable:	0,00



Seat cover FL, Tear, Replace

657,31



Engine insulation, Damaged, Replace

151,41



Bumper F, Scratch(es), Acceptable

0,00



Bonnet, Chemical polution, Repair and paint (complete)

395,90



Windscreen, Stone chip(s), Replace

0,00



Door seal FL, Broken, Replace

131,55



Alloy rim RL, Scratch(es), Repair and paint (complete)

129,64



Internal boot lining L, Scratch(es), Replace

200,64

Internal boot lining L, Scratch(es), Replace

200,64



Internal boot lining L, Tear, Replace

200,64



Internal boot lining R, Scratch(es), Replace

203,46



Boot lid covering R, Scratch(es), Replace

154,61



Bumper R, Scratch(es), Repair and paint (complete)

289,07



Rear window, Scratch(es), Replace

0,00



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)

420,65





Door RR, Chemical polution, Polish

0,00

