

VW PASSAT SPORTSCOMBI GTE 1.4 TSI ACT OPF

Vehicle information

License plate	OUM63P	Inspected by	A.A.
Year model	2021	Date of inspection	2025-01-27
Manuf. year/month	2021-06	City	Björkvik
First day in traffic	2021-06	Keys	2
Colour	Silver	Service book	Elektronisk servicebok
Mileage	93 330 km	Latest service	2024-09-10
Fuel	Elhybrid	Mileage at the latest service	88 720 km
Transmission	DSG Sekventiell	Summer tires	18" alu-fälg 5/5/5/5
Engine effect	115 kW	Winter tires	alu-fälg odubbat 7/5/5/7

Damages

Location	Damage	Comments	Costs excluding VAT
Exterior	Normalt slitage		-
Rear bumpers	Normalt slitage	Lastrepor	-
Baklucka	Spot repair	Buckla på TAKVINGE	180)
Tak, 1 Damage	Lackering	Buckla	620)
Front bumpers, 1 Damage	Lackering	Skrapad	560)
Baklucka	Spot repair	Små buckla	180)
Däck/Fälg, Rims	Skrapmärken, Spot repair	Hb	180)

Total excl. VAT	1720
-----------------	------

Service occasions

Fordonet ska tvättas

Images

[See all images in large format](#)

















Serviceprotokoll

Registrering: 2022-01-03

Registreringsnr: OUM63P

Modellkod: CB56YY

Mätarställning: 88727

Servicerådgivare: AB

Arsmoell: 2021

Datum: 20240910

2183

MMB

DGEB

VMB

UQ5

1.5 TSID6F

Inspektion med oljebyte

	Ok/genomförd	Inte ok	åtgärdat
innertaket, bagagerums- och handskfacksbelysning:	☒	☐	☐
tionen	☒	☐	☐
ollera funktionen	☒	☐	☐
llera att den finns och inte har synliga skador			

Ok/genomförd

Inte ok

åtgärdat

halvliis, helljus,










Exteriör Normalt slitage



Stötfångare bak Normalt slitage Lastrepor



Baklucka Spot repair Buckla på TAKVINGE 2 000 kr



Tak 1 Skada Lackering Buckla 6 922 kr



Stötfångare fram 1 Skada Lackering Skrapad 6 210 kr



Baklucka Spot repair Små buckla 2 000 kr



Däck/Fälg Fälg Skrapmärken, Spot repair Hb 2 000 kr



