

# Inspection Protocol

## VW PASSAT ALLTRACK 2.0 TDI DPF SCR 4MOTION

### Vehicle information

<b>License plate</b>	NTF53D	<b>Inspected by</b>	C.C.
<b>Year model</b>	2022	<b>Date of inspection</b>	2025-10-23
<b>Manuf. year/month</b>	2022-04	<b>City</b>	Björkvik
<b>First day in traffic</b>	2022-04	<b>Keys</b>	2
<b>Colour</b>	Mörkgrå	<b>Service book</b>	Elektronisk servicebok
<b>Mileage</b>	119 290 km	<b>Latest service</b>	-
<b>Fuel</b>	Diesel	<b>Mileage at the latest service -</b>	
<b>Transmission</b>	DSG Sekventiell	<b>Summer tires</b>	18" alu-fälg 3/3/3/3
<b>Engine effect</b>	147 kW	<b>Winter tires</b>	alu-fälg dubbat 7/7/7/7

### Damages

Location	Damage	Comments	Costs excluding VAT
Door, Front left	Repa/Repor		150 €
Bumper, Rear	Repa/Repor		260 €
Boot lid, Boot lid	Repa/Repor		150 €
Skärm , Rear right	Repa/Repor		260 €
Door, Rear right	Repa/Repor		150 €
Door, Front right	Repa/Repor		150 €
Bumper, Front	Liten buckla/Repor		330 €
Bonnet, Bonnet	Liten buckla/Repor		290 €
Glass, Windshield	Stenskott/Spricka	Det finns ingen skadeanmälan	510 €
Tak, Tak	Smart repair	Lackskada	70 €

---

**Total excl. VAT** 2 320 €

### Images

[See all images in large format](#)






























Dörr Vänster fram Repa/Repor 2 000 kr



Stötfångare Bak Repa/Repor 3 500 kr





Bagagelucka Bagagelucka Repa/Repor 2 000 kr



Skärm Höger bak Repa/Repor 3 500 kr



Dörr Höger bak Repa/Repor 2 000 kr



Dörr Höger fram Repa/Repor 2 000 kr



Stötfångare Fram Liten buckla/Repor 4 500 kr



Motorhuv Motorhuv Liten buckla/Repor 4 000 kr



Glas Vindruta Stenskott/Spricka Det finns ingen skadeanmälan 7 000 kr



Tak Tak Smart repair Lackskada 1 000 kr