



VOLKSWAGEN POLO: 1VMP537

Vinnumber:	WVWZZZAWZKY000800	Versionname:	1.0 TSI Comfortline
First Registrationdate:	2/01/2019	Fiscalpower:	
Expertise Mileage:	91937	Power Kw:	70
Bodytype:		Body colour:	Black
Gearbox:	MAN 5 VIT	Type of rims (mounted):	Steel
Transmission:		Parking lot:	1205
Fueltype:	Petrol		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Type of Tow bar:	No Tow bar
Steering wheel multifunctional:			
Radio multimedia:			
Type of headlighting:	Headlighting Halogen		
Type of GPS:	No GPS		
Type of Lining:	Lining fabrics		
Type of climate control:	Manual climate control		

Limited Technical Inspection

Degree of wear

185/65/15/88 H				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Hankook: 5 mm	Re.R.	Hankook: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				185/65 R 15 88 H
Tyre size FR				185/65 R 15 88 H
Tyre size RL				185/65 R 15 88 H
Tyre size RR				185/65 R 15 88 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				260
Tyre make RR				260

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT	1040,94
Bumper F, Scratch(es), Repair and paint (complete)	231,25



Bumper moulding F, Broken, Replace 188,97



Windscreen, Scratch(es), Replace 0,00



Door RL, Dent(s), Repair and paint (complete) 347,59



Wheel cover RL, Not original part, Acceptable 0,00



Wing FL, Scratch(es), Acceptable 0,00



Wheel cover FL, Not original part, Acceptable 0,00



Bumper R, Scratch(es), Repair and paint (complete) 231,25



Wheel cover FR, Not original part, Acceptable 0,00



Wing RR, Scratch(es), Acceptable 0,00



Wheel cover RR, Not original part, Acceptable

0,00



Aerial, Missing, Replace

41,88

