

Inspection Protocol



VW POLO 1.0 TSI OPF DSG

Vehicle information

License plate	THK77A	Inspected by	C.C.
Year model	2020	Date of inspection	2025-04-14
Manuf. year/month	2020-08	City	Björkvik
First day in traffic	2020-09	Keys	2
Colour	Vit	Service book	Elektronisk servicebok
Mileage	94 630 km	Latest service	-
Fuel	Bensin	Mileage at the latest service -	
Transmission	DSG Sekventiell	Summer tires	15" alu-fälg 4/4/5/5
Engine effect	70 kW	Winter tires	plåtfälg dubbat 6/6/6/6

Damages

Location	Damage	Comments	Costs excluding VAT
Instrument, Stereo	Defective		-
Service	Due now		360 €
Inredning, Drivers seat	Tears		140 €
Recond	Interior		60 €
Rims & Tires, Summer	Rim damage 4 wheel		430 €
Inredning, Boot	Other	Hatthylla saknas	-
Door, Front left	Dent above 100 mm		250 €
Door, Rear left	Dents 30-100 mm		210 €
Wing, Rear left	Dents below 30 mm		60 €
Bumper, Rear	Scratches above 100 mm		180 €
Wing, Rear right	Dents below 30 mm		60 €
Door, Rear right	Scratches below 30 mm		60 €
Door, Front right	Dents below 30 mm		60 €
Wing, Front right	Scratches below 30 mm		60 €
Bumper, Front	Dents		240 €
Lamps, Headlights	Other	Repa	-
Other, Other	Regskylt fram inbuktningar		10 €

Total excl. VAT	2 180 €
-----------------	---------

Service occasions

5000-MIL, 7000-MIL, 7500-MIL

Images

[See all images in large format](#)









Inredning Bagageutrymme Övrigt Hatthylla saknas



Service Dags nu 5 000 kr



Instrument Ljudanläggning Ur funktion





Inredning Vänster framstol Revor 2 000 kr





Rekonst Invändig 800 kr







Fälgar & Däck Sommar Fälgskada 4 hjul 6 000 kr





Dörr Vänster fram Bucklor över 10 cm 3 500 kr



Dörr Vänster bak Bucklor 3-10 cm 2 900 kr





Skärm Vänster bak Bucklor under 3 cm 800 kr



Stötfångare Bak Repor över 10 cm 2 500 kr



Skärm Höger bak Bucklor under 3 cm 800 kr



Dörr Höger bak Repor under 3 cm 800 kr



Dörr Höger fram Bucklor under 3 cm 800 kr



Skärm Höger fram Repor under 3 cm 800 kr



Stötfångare Fram Inbuktningar 3 300 kr







Lampor Huvudstrålkastare Övrigt Repa



Övrigt Övrigt Regskylt fram inbuktningar 100 kr



