



**Volkswagen Golf: 2BUS805**

Vinnumber:	<b>WVWZZZCDZNW160489</b>	Versionname:	
First Registrationdate:	<b>30/03/2022</b>	Fiscalpower:	
Expertise Mileage:	<b>41683</b>	Power Kw:	<b>81</b>
Bodytype:		Body colour:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>1120</b>
Fueltype:	<b>Petrol</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Number of keys total:	<b>2</b>	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Radio multimedia:		Type of Tow bar:	<b>No Tow bar</b>
Type of headlighting:	<b>Headlighting LED</b>		
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining fabrics</b>		
Type of climate control:	<b>Autom climate control</b>		

**Limited Technical Inspection**

**Degree of wear**

205/55/16/92 H			
Winter tyres:	Fr.L. Goodyear: 5 mm	Fr.R. Goodyear: 5 mm	
	Re.L. Goodyear: 5 mm	Re.R. Goodyear: 5 mm	
Tyre profile depth FL			5.0
Tyre profile depth FR			5.0
Tyre profile depth RL			5.0
Tyre profile depth RR			5.0
Tyre size FL			205/55 R 16 92 H
Tyre size FR			205/55 R 16 92 H
Tyre size RL			205/55 R 16 92 H
Tyre size RR			205/55 R 16 92 H
Tyre type FL			Winter
Tyre type FR			Winter
Tyre type RL			Winter
Tyre type RR			Winter
Tyre make FL			259
Tyre make FR			259
Tyre make RL			259
Tyre make RR			259

**Assistance equipment**

Spare wheel:	<b>Yes</b>	Jack:	<b>Yes</b>
Number of charging cables (normal):	<b>0</b>		
Number of charging cables (rapid charge):	<b>0</b>		

<b>Total cost ex VAT</b>	<b>2351,09</b>
<b>Dashboard, Glue residues, Cleaning</b>	<b>28,43</b>



Bonnet, Chemical polution, Repair and paint (complete)

627,90



Wheel cover RL, Missing, Replace

25,00



Wheel cover FL, Missing, Replace

25,00



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)

347,07



Roof pillar R, Hail damage, Repair and paint (complete)

300,51



Wheel cover FR, Missing, Replace

25,00



Wheel cover RR, Missing, Replace

25,00



Bodywork, Not original part, Remove lettering

0,00



Roof, Chemical polution, Repair and paint (complete)

947,18

