

Inspection Protocol



TESLA MODEL Y LONG RANGE AWD, 514HK, 2023

Vehicle information

License plate	AHK17J	Inspected by	S.V.
Year model	2023	Date of inspection	2025-10-30
Manuf. year/month	2023-03	City	Falkenberg
First day in traffic	2023-03	Keys	2
Colour	Svart	Service book	Elektronisk servicebok
Mileage	110 940 km	Latest service	-
Fuel	El (EV)	Mileage at the latest service-	
Transmission	Automat	Summer tires	20" alu-fälg 5/3/3/5
Engine effect	378 kW	Winter tires	alu-fälg odubbat 6/6/7/7

Damages

Location	Damage	Comments	Costs excluding VAT
Rims & Tires, Winter	Rim damage 2 wheel		220 €
Wing, Front left	Scratches below 30 mm		60 €
Tak, Sun roof	Other	Stenskott	-
Bumper, Rear	Repor, 3-10 cm		80 €
Boot lid, Boot lid	Paint retouch traces		-
Insteg, Rear right	Scratches		60 €
Wing, Front right	Scratches below 30 mm		60 €
Bumper, Front	Scratches below 30 mm	Samt stenskott	60 €
Bonnet	Chips, several		160 €
Glass, Windshield	Chip		20 €
Rims & Tires, Summer	Rim damage 3 wheel		330 €

Total excl. VAT 1 050 €

Images


[See all images in large format](#)













Aktuell körning Åkerstäl		
Avstånd	Tidslängd	Snittförbrukning
0,0 km	4 min	---- Wh/km


Sedan sluta ledning		
Avstånd	Total energi	Snittförbrukning
101,0 km	33,1 kWh	102,9 Wh/km



Resor A Åkerstäl		
Avstånd	Total energi	Snittförbrukning
0,0 km	0,0 kWh	---- Wh/km

Resor B Åkerstäl		
Avstånd	Total energi	Snittförbrukning
0,0 km	0,0 kWh	---- Wh/km

Vägmätare : 110 945 km













Fälgar & Däck Vinter Fälgskada 2 hjul 3 000 kr



Skärm Vänster fram Repor under 3 cm 800 kr



Tak Glastak Övrigt Stenskott



Stötfångare Bak Repor, 3-10 cm 1 100 kr



Bagagelucka Bagagelucka Lackbättring



Insteg Höger bak Repor 800 kr



Skärm Höger fram Repor under 3 cm 800 kr



Stötfångare Fram Repor under 3 cm Samt stenskott 800 kr



Motorhuv Stenskott flertal 2 200 kr



Glas Vindruta Stenskott 300 kr







Fälgar & Däck Sommar Fälgskada 3 hjul 4 500 kr