

Inspection Protocol

VOLVO XC60 RECHARGE T6 AWD

Vehicle information

License plate	DCO095	Inspected by	C.C.
Year model	2023	Date of inspection	2025-11-26
Manuf. year/month	2022-09	City	Björkvik
First day in traffic	2022-09	Keys	2
Colour	Svart	Service book	Ja
Mileage	149 710 km	Latest service	2025-05-14
Fuel	Elhybrid	Mileage at the latest service	125 140 km
Transmission	Geartronic	Summer tires	18" alu-fälg 5/5/5/6
Engine effect	257 kW	Winter tires	alu-fälg dubbat 8/8/8/8

Damages

Location	Damage	Comments	Costs excluding VAT
Recond, Animal hairs	Sanering		110 €
Skärm , Front left	Repa/Repor		150 €
Door, Front left	Repa/Repor		150 €
Door, Rear left	Repa/Repor		150 €
Skärm , Rear left	Repa/Repor		250 €
Bumper, Rear	Repa/Repor		250 €
Boot lid, Boot lid	Repa/Repor		150 €
Skärm , Rear right	Repa/Repor		250 €
Door, Rear right	Repa/Repor		150 €
Door, Front right	Repa/Repor		150 €
Skärm , Front right	Repa/Repor		150 €
Bumper, Front	Repa/Repor		540 €
Bonnet, Bonnet	Repa/Repor		540 €
Tak, Tak	Repa/Repair		330 €
Tak, Sun roof	Damage		1 090 €
Recond, Dirty trim	Klädsel tvätt		150 €
Total excl. VAT			4 560 €

Images

[See all images in large format](#)


























Rekond Djurhår Sanering 1 500 kr






















Skärm Vänster fram Repa/Repor 2 000 kr



Dörr Vänster fram Repa/Repor 2 000 kr




Dörr Vänster bak Repa/Repor 2 000 kr





Skärm Vänster bak Repa/Repor 3 500 kr



Stötfångare Bak Repa/Repor 3 500 kr



Bagagelucka Bagagelucka Repa/Repor 2 000 kr





Skärm Höger bak Repa/Repor 3 500 kr





Dörr Höger bak Repa/Repor 2 000 kr





Dörr Höger fram Repa/Repor 2 000 kr




Skärm Höger fram Repa/Repor 2 000 kr



Stötfångare Fram Repa/Repor 7 500 kr





Motorhuv Motorhuv Repa/Repor 7 500 kr



Tak Tak Repa/Repair 4 500 kr



Tak Glastak Skada 15 000 kr





Rekon. Smutsig klädsel Klädsel tvätt 2 000 kr