![DEKRA Automotive Solutions logo]

![Ayvens - Societe Generale Group logo]

Vehicle details

VIN	KNACC81CG L5386283	Brand	KIA	Maintenance date	-
Licence Plate	J6-23-DR	Model	Niro 1.6 GDi Hybrid ActieAuto 5d DynamicLine APL	Maintenance mileage	-
Registration date	11/07/2020	Year	2020	Exterior Color	White Solid
Odometer	69 812 km	Engine size	1580	interior Color	Grey
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	18/07/2025	Inspection loc.	Dekra Ayvens

Generic equipment

|	
Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓

Removable element

Spare wheel (wheel & tyre)	✓
Load cover	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Pirelli 205/60/16 Summer 7.0 mm	Pirelli 205/60/16 Summer 7.5 mm
Michelin 205/60/16 Summer 6.0 mm	Michelin 205/60/16 Summer 6.0 mm

Exterior

1		Part	Roof
		Position	-
		Damages	Dented
		Severity	Diameter (mm) > 20
		Repair mode	Smart Repair

2		Part	Wing
		Position	Front right
		Damages	Dented
		Severity	Diameter (mm) > 20
		Repair mode	Smart Repair

3		Part	Door
		Position	Back right
		Damages	Dented
		Severity	Diameter (mm) > 20
		Repair mode	Smart Repair

4		Part	Step plate
		Position	Back right
		Damages	Dent & Chips
		Severity	-
		Repair mode	For info

5		Part	Lower bumper
		Position	Back
		Damages	Scratched
		Severity	Length (cm) > 10
		Repair mode	Repair

6		Part	Door
		Position	Back left
		Damages	Dented
		Severity	Diameter (mm) > 20
		Repair mode	Smart Repair

7		Part	Step plate
		Position	Back left
		Damages	Dent & Chips
		Severity	-
		Repair mode	For info