Vehicle details

| | | | | | | |
|---|---|---|---|---|---|
| VIN | TMBJJ8NX0 PY019276 | Brand | SKODA | Maintenance date | - |
| Licence Plate | W25456N | Model | OCTAVIA 2.0 Tdi 150 Ps Style Combi 6-Gang 110KW | Maintenance mileage | - |
| Registration date | 18/10/2022 | Year | 1000 | Exterior Color | White Solid |
| Odometer | 33 023 km | Engine size | 1968 | interior Color | Black |
| Fuel | Diesel | Body Type | Estate | Next technical inspection | 01/10/2025 |
| Seats | - | Transmission | Manual | CO2 | - |
| Doors | 5 | Gears | - | | |

Inspection Details

Inspection date	18/11/2025	Inspection loc.	Hödlmayr Logistics GmbH

Generic equipment

Automated air-conditioning	✔
Cruise control	✔
Rain and light sensor	✔
GPS system	✔
Xenon projectors	✔
Anti-fog lights	✔
Front radars	✔
Alloy wheel rims	✔
Reversing radars	✔
Reversing camera	✔

Removable element

Technical Document

Service manual holder	✔
User manual	✔
Spare key	✔
Remote key	✔

Tyres

Winter kit

Michelin 205/55/17 H Winter 5.9 mm		Michelin 205/55/17 H Winter 6.4 mm	
Michelin 205/55/17 H Winter 7.8 mm		Michelin 205/55/17 H Winter 7.6 mm	

Exterior

1

Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Repair

2

Part	Bonnet
Position	-
Damages	Dented
Severity	-
Repair mode	Repair

3

Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	Repair

Others

4

Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Paintworks

5

Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Plastic paint